

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167274010000

Project: SWIW-2-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that well is not in operation at this time,owner is currently hauling water too there other facility in Noble county.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 175 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/6/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner BIG INJUN OIL & GAS INC.

Former Owners

12/30/1982 118 BIG INJUN OIL & GAS INC GeoDate 12/30/82

12/13/1984 642 LOTHES OIL & GAS INC GeoDate 12/13/84

5/3/1989 3133 PETROEL GeoDate 5/3/89

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167279580000

Project: SWIW-9-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN(SWIW#9) No.: 3 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that well is currently not being used.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 165 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/6/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner CARPER WELL SERVICE

Former Owners

12/20/1984 3133 PETROEL GeoDate 12/20/84

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pumps were in operation and it was noted that nine Hall Drilling vacuum trucks were unloading at the facility during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1160 Vac ANNULUSPRESSURE: 100 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/6/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness pressure testing of new flow line it is 2500psi rated flex steel line and we pressure tested it at 1380 psi and monitored pressure for 30 minutes with no decline in pressure.

Note: Four Hall Drilling vacuum trucks were unloading at the facility during my inspection and it was noted that permanent facility is nearly complete.

Accompanied by _____

INJECTIONPRESSUR 950 Vac ANNULUSPRESSURE: 155 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/15/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was not in operation during my inspection.

Noted small slip development at the route seven offload site and I talked to Shaun Cass and he stated they had a contractor out to look at slip area and give them cost estimate on repair work.

Accompanied by _____

INJECTIONPRESSUR 210 Vac ANNULUSPRESSURE: 330 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/15/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was not in operation during my inspection.

Noted small slip development at the route seven offload site and I talked to Shaun Cass and he stated they had a contractor out to look at slip area and give them cost estimate on repair work.

Accompanied by _____

INJECTIONPRESSUR 400 Vac ANNULUSPRESSURE: 600 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/15/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was not in operation during my inspection.

Noted small slip development at the route seven offload site and I talked to Shaun Cass and he stated they had a contractor out to look at slip area and give them cost estimate on repair work.

Accompanied by _____

INJECTIONPRESSUR 380 Vac ANNULUSPRESSURE: 550 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/15/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296850000

Project: SWIW-10-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: NEWELL RUN DISPOSAL WELL(S) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump to this well was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1800 Vac ANNULUSPRESSURE: 210 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/14/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296580000

Project: SWIW-8-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: LONG RUN DISPOSAL WELL(SWI No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump to this well was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1590 Vac ANNULUSPRESSURE: 500 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/14/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that well is not in operation at this time ,owner is planning on plugging well back at some point in time.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1600 Vac ANNULUSPRESSURE: 600 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/14/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295770000

Project: SWIW-7-WASH

County: WASHINGTON Twp. LAWRENCE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: FQ ENERGY SERVICES LLC Resp Co

Well Name: HELEN F HALL (SWIW #7) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1800 Vac ANNULUSPRESSURE: 85 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/14/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

10/24/2014 Operator changed from 7434, VIRCO INC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296180000

Project: SWIW-15-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: FQ ENERGY SERVICES LLC Resp Co

Well Name: GREENWOOD UNIT (SWIW #15) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Address

Inspection Purpose: Status Check

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that clean up of area of recent spill is final and well is still incapable of injection in its present state of repair injection pump is missing and they had communication between tubing and packer when well was in operation.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1200 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/14/2016

Signature:

Date Compliance Issued:

DAVID BALL

Required action to be completed by:

Reviewed by:

Extended action completed:

Forward to:

Required action completed:

Duration: _____

hrs

Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

3/24/2010 Operator changed from 2348, TRIAD RESOURCES INC to 8610, TRIAD HUNTER LLC

12/21/2011 Operator changed from 8610, TRIAD HUNTER LLC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pumps were not in operation during my inspection and it was noted that one Deepwell tanker was unloading at the state route 7 facility during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 700 Vac ANNULUSPRESSURE: 580 Vac FLOWMETER: Vac

HAULERNO: 25659 LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/13/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pumps were not in operation during my inspection and it was noted that one Deepwell tanker was unloading at the state route 7 facility during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 600 Vac ANNULUSPRESSURE: 680 Vac FLOWMETER: Vac

HAULERNO: 25659 LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/13/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pumps were not in operation during my inspection and it was noted that one Deepwell tanker was unloading at the state route 7 facility during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 760 Vac ANNULUSPRESSURE: 610 Vac FLOWMETER: Vac

HAULERNO: 25659 LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/13/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167274010000

Project: SWIW-2-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Well not in operation at this time.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 185 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/14/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner BIG INJUN OIL & GAS INC.

Former Owners

12/30/1982 118 BIG INJUN OIL & GAS INC GeoDate 12/30/82

12/13/1984 642 LOTHES OIL & GAS INC GeoDate 12/13/84

5/3/1989 3133 PETROEL GeoDate 5/3/89

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167279580000

Project: SWIW-9-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN(SWIW#9) No.: 3 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Well not in operation at this time.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 185 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/14/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner CARPER WELL SERVICE

Former Owners

12/20/1984 3133 PETROEL GeoDate 12/20/84

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167293950000

Project: SWIW-6-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: OHIO OIL GATHERING CORP II (S No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump to this well was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/14/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner APPALACHIAN OIL PURCHASERS INC

Former Owners

7/6/2001 Operator changed from 6357, APPALACHIAN OIL PURCHASERS INC to 2153, OOGC DISPOSAL CO #1

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation and it was noted that four Hall Drilling vacuum trucks were unloading at the facility during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1275 Vac ANNULUSPRESSURE: 980 Vac FLOWMETER: Vac

HAULERNO: 25361 LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/13/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation and it was noted that two Energy Transport trucks were unloading at the facility today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1010 Vac ANNULUSPRESSURE: 135 Vac FLOWMETER: Vac

HAULERNO: 25601 LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/1/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that well is down due to lack of water.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 25 Vac ANNULUSPRESSURE: 580 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/1/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was not in operation and it was noted that one Summit Transport vacuum truck was unloading at the state route facility during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 680 Vac ANNULUSPRESSURE: 590 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/1/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was not in operation and it was noted that one Summit Transport vacuum truck was unloading at the state route facility during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 660 Vac ANNULUSPRESSURE: 440 Vac FLOWMETER: Vac

HAULERNO: 25349 LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/1/2016

Signature: _____

Date Compliance Issued:

DAVID BALL

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was not in operation and it was noted that one Summit Transport vacuum truck was unloading at the state route facility during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 620 Vac ANNULUSPRESSURE: 400 Vac FLOWMETER: Vac

HAULERNO: 25349 LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/1/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295770000

Project: SWIW-7-WASH

County: WASHINGTON Twp. LAWRENCE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: FQ ENERGY SERVICES LLC Resp Co

Well Name: HELEN F HALL (SWIW #7) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was running and it was noted that one company owned vacuum truck was at the site during my inspection.

Note: Roll off box at site needs to be emptied it contains used filters.

Accompanied by _____

INJECTIONPRESSUR 1770 Vac ANNULUSPRESSURE: 80 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/15/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

10/24/2014 Operator changed from 7434, VIRCO INC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Well not in operation at this time.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 900 Vac ANNULUSPRESSURE: 650 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/15/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296580000

Project: SWIW-8-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: LONG RUN DISPOSAL WELL(SWI No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump too this well was in operation today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1610 Vac ANNULUSPRESSURE: 480 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/15/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296850000

Project: SWIW-10-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: NEWELL RUN DISPOSAL WELL(S) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pumps to this well was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1870 Vac ANNULUSPRESSURE: 240 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/15/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296180000

Project: SWIW-15-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: FQ ENERGY SERVICES LLC Resp Co

Well Name: GREENWOOD UNIT (SWIW #15) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Waiting on service rig to plug said well.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/15/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

3/24/2010 Operator changed from 2348, TRIAD RESOURCES INC to 8610, TRIAD HUNTER LLC

12/21/2011 Operator changed from 8610, TRIAD HUNTER LLC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167293950000

Project: SWIW-6-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: OHIO OIL GATHERING CORP II (S No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation and it was noted that three Waste Management tankers were unloading at the terminal today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1860 Vac ANNULUSPRESSURE: 320 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/15/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner APPALACHIAN OIL PURCHASERS INC

Former Owners

7/6/2001 Operator changed from 6357, APPALACHIAN OIL PURCHASERS INC to 2153, OOGC DISPOSAL CO #1

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was not in operation during my inspection.
Walked flowline area to monitor area for any leakage none were found.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 880 Vac ANNULUSPRESSURE: 190 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/5/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167279580000

Project: SWIW-9-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN(SWIW#9) No.: 3 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that well is currently not in operation due to lack of brine hauling activity.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 165 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/6/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner CARPER WELL SERVICE

Former Owners

12/20/1984 3133 PETROEL GeoDate 12/20/84

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167274010000

Project: SWIW-2-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that well is currently not in operation due to lack of brine hauling activity.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 160 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/6/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner BIG INJUN OIL & GAS INC.

Former Owners

12/30/1982 118 BIG INJUN OIL & GAS INC GeoDate 12/30/82

12/13/1984 642 LOTHES OIL & GAS INC GeoDate 12/13/84

5/3/1989 3133 PETROEL GeoDate 5/3/89

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that well is currently not being used due to lack of disposal clients.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 25 Vac ANNULUSPRESSURE: 590 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/5/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pups were in operation and it was noted that slip area at the route seven facility still needs to be addressed when litigation procedures are completed.

Note: Brine haulers 25-459 and 25-361 and 25-588 were unloading at the facility during my inspection.

Accompanied by _____

INJECTIONPRESSUR 1340 Vac ANNULUSPRESSURE: 260 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/5/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone
Address

Inspection Purpose: Status Check

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pups were in operation and it was noted that slip area at the route seven facility still needs to be addressed when litigation procedures are completed.

Note: Brine haulers 25-459 and 25-361 and 25-588 were unloading at the facility during my inspection.

Accompanied by _____

INJECTIONPRESSUR 1240 Vac ANNULUSPRESSURE: 220 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/5/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pups were in operation and it was noted that slip area at the route seven facility still needs to be addressed when litigation procedures are completed.

Note: Brine haulers 25-459 and 25-361 and 25-588 were unloading at the facility during my inspection.

Accompanied by _____

INJECTIONPRESSUR 1320 Vac ANNULUSPRESSURE: 240 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/5/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation today and it was noted that one Hall Drilling tanker was at the site offloading during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1275 Vac ANNULUSPRESSURE: 975 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/5/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Note: Met with owner to discuss slip issue on hill above storage tank area and they stated that they have contacted engineering firm to formulate plan for repair and we also discussed placing steel roofs on large storage tanks at the state route seven facility and also 676 storage area.

Accompanied by _____

INJECTIONPRESSUR 1320 Vac ANNULUSPRESSURE: 300 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/17/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Note: Met with owner to discuss slip issue on hill above storage tank area and they stated that they have contacted engineering firm to formulate plan for repair and we also discussed placing steel roofs on large storage tanks at the state route seven facility and also 676 storage area.

Accompanied by _____

INJECTIONPRESSUR 1240 Vac ANNULUSPRESSURE: 240 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/17/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC

12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC

12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.

12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC

12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone
Address

Inspection Purpose: Status Check

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Note: Met with owner to discuss slip issue on hill above storage tank area and they stated that they have contacted engineering firm to formulate plan for repair and we also discussed placing steel roofs on large storage tanks at the state route seven facility and also 676 storage area.

Accompanied by _____

INJECTIONPRESSUR 1310 Vac ANNULUSPRESSURE: 250 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/17/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection and it was noted that brine hauler 25-601 was unloading at the facility during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 920 Vac ANNULUSPRESSURE: 130 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/17/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167293950000

Project: SWIW-6-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: OHIO OIL GATHERING CORP II (S No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump to this well was in operation today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1860 Vac ANNULUSPRESSURE: 330 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/6/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner APPALACHIAN OIL PURCHASERS INC

Former Owners

7/6/2001 Operator changed from 6357, APPALACHIAN OIL PURCHASERS INC to 2153, OOGC DISPOSAL CO #1

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pumps were not in operation during my inspection.

Note: Brine hauler 25-651 and 25-453 were unloading at the state route 7 facility during my inspection of the offloading site.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 650 Vac ANNULUSPRESSURE: 450 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/30/2016

Signature: _____

Date Compliance Issued: _____

DAVID BALL

Required action to be completed by: _____

Reviewed by: _____

Extended action completed: _____

Forward to: _____

Required action completed: _____

Duration: _____ hrs

Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pumps were not in operation during my inspection.

Note: Brine hauler 25-651 and 25-453 were unloading at the state route 7 facility during my inspection of the offloading site.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 600 Vac ANNULUSPRESSURE: 390 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/30/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pumps were not in operation during my inspection.

Note: Brine hauler 25-651 and 25-453 were unloading at the state route 7 facility during my inspection of the offloading site.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 640 Vac ANNULUSPRESSURE: 400 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/30/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone
Address

Inspection Purpose: Status Check

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pumps were in operation today.

Note: State route 7 unloading facility had numerous trucks waiting to offload today.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1050 Vac ANNULUSPRESSURE: 400 Vac FLOWMETER: Vac

HAULERNO: 25588 LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/13/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pumps were in operation today.

Note: State route 7 unloading facility had numerous trucks waiting to offload today.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 980 Vac ANNULUSPRESSURE: 400 Vac FLOWMETER: Vac

HAULERNO: 25601 LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/13/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296850000

Project: SWIW-10-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: NEWELL RUN DISPOSAL WELL(S) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump to this well was in operation today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1870 Vac ANNULUSPRESSURE: 250 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/6/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296580000

Project: SWIW-8-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: LONG RUN DISPOSAL WELL(SWI No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump to this well was in operation today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1600 Vac ANNULUSPRESSURE: 465 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/6/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump to this well was not in operation at the time of my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1830 Vac ANNULUSPRESSURE: 565 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/6/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone
Address

Inspection Purpose: Status Check

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pumps were in operation today.

Note: State route 7 unloading facility had numerous trucks waiting to offload today.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1050 Vac ANNULUSPRESSURE: 280 Vac FLOWMETER: Vac

HAULERNO: 25361 LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/13/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: BROAD STREET SERV LLC Resp Co

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation today and it was noted that one H&L tanker was unloading at the facility and one Waste Management vacuum truck was also unloading at the facility during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 900 Vac ANNULUSPRESSURE: 250 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/8/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

- 12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86
- 4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89
- 9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89
- 11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89
- 10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY
- 2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC
- 7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was not in operation today and it was noted that brine hauler#25-568 was unloading at the facility during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 540 Vac ANNULUSPRESSURE: 400 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/8/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Production Wells Contact: Phone

Inspection Purpose: Request Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspected site for possible conversion to SWIW well.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/16/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Production Wells Contact: Phone

Inspection Purpose: Request Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspected well for possible conversion to SWIW and in conversation with owner stating that he would like to get started on this project soon.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/16/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: BROAD STREET SERV LLC Resp Co

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump has been replaced and was in operation during my inspection and it was noted that two Oil Haulers vacuum trucks were unloading at the facility on this day of my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1000 Vac ANNULUSPRESSURE: 250 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/23/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: BROAD STREET SERV LLC Resp Co

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that well is not in operation at this time due too injection pump is being rebuilt.
Note: Told operator when weather gets better they will need to repair lease road to the well head.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 700 Vac ANNULUSPRESSURE: 300 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/4/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167279580000

Project: SWIW-9-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN(SWIW#9) No.: 3 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that owner has completed remedial work required at site and is ready to place wells on the lease back into operation.

Note: Witnessed MIT testing on annulus of tubing today owner applied 550 psi and we monitored pressure for 15 minutes with no decline in pressure.

Dike measurements are as follows 25'X50'X48" TALL with a calculated volume of 888 bbl.

Accompanied by _____

INJECTIONPRESSUR 0 Vac ANNULUSPRESSURE: 550 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/23/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner CARPER WELL SERVICE

Former Owners

12/20/1984 3133 PETROEL GeoDate 12/20/84

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167279580000

Project: SWIW-9-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN(SWIW#9) No.: 3 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that well is not in operation at this time, owner has rebuilt facility and they are waiting on better weather so they can cover exposed portions of containment liner so it wont rot due to exposure to the sunlight.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 0 Vac ANNULUSPRESSURE: 450 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/2/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner CARPER WELL SERVICE

Former Owners

12/20/1984 3133 PETROEL GeoDate 12/20/84

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was not in operation during my inspection and it was noted that one H&L Water Service vacuum truck was unloading at the facility during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 560 Vac ANNULUSPRESSURE: 620 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/23/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was not in operation during my inspection and it was noted that company has fresh water build up within containment area and it needs to be pumped into storage tanks and disposed of.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 630 Vac ANNULUSPRESSURE: 525 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/4/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167274010000

Project: SWIW-2-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that owner has completed remedial work required at site and is ready to place wells on the lease back into operation.

Note: Witnessed MIT testing on annulus of tubing today owner applied 550 psi and we monitored pressure for 15 minutes with no decline in pressure.

Dike measurements are as follows 25'X50'X48" TALL with a calculated volume of 888 bbl.

Accompanied by _____

INJECTIONPRESSUR 0 Vac ANNULUSPRESSURE: 550 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/23/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner BIG INJUN OIL & GAS INC.

Former Owners

12/30/1982 118 BIG INJUN OIL & GAS INC GeoDate 12/30/82

12/13/1984 642 LOTHES OIL & GAS INC GeoDate 12/13/84

5/3/1989 3133 PETROEL GeoDate 5/3/89

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167274010000

Project: SWIW-2-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that well is not in operation at this time, owner has rebuilt facility and they are waiting on better weather so they can cover exposed portions of containment liner so it wont rot due to exposure to the sunlight.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 0 Vac ANNULUSPRESSURE: 480 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/2/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner BIG INJUN OIL & GAS INC.

Former Owners

12/30/1982 118 BIG INJUN OIL & GAS INC GeoDate 12/30/82

12/13/1984 642 LOTHES OIL & GAS INC GeoDate 12/13/84

5/3/1989 3133 PETROEL GeoDate 5/3/89

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness running of the remainder tubing string and pressure testing of the annulus of tubing, Universal Well Service performed pressure test@1540 psi with zero loss in pressure(TEST PASSED).

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: 1540 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/17/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Production Wells Contact: Phone

Inspection Purpose: Request Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness Baker A-3 set lock and 2.875" tubing start in hole preparing to convert well to SWIW well on this day we ran 5400' of tubing and they will finish running it tomorrow and setting depth will be approximately 6200'

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/16/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Production Wells Contact: Phone
Inspection Purpose: Status Check Address
Type of Notification Contact DAVID BALL

Inspection Comments:

Onsite to witness tubing and packer run into well and setting depth was 6102' and packer was set in 14k compression and we tested it at 1560 psi with no decline in pressure and then we bled pressure off to 560 psi and shut well in once we blew off the blank disk on the bottom of packer.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/19/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Production Wells Contact: Phone
Address

Inspection Purpose: Request

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness packer and tubing run into well, company owned rig ran 3500' today and we should be ready to set packer tomorrow and perform MIT test in preparation to convert well to SWIW well.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/18/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295770000

Project: SWIW-7-WASH

County: WASHINGTON Twp. LAWRENCE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: GREEN HUNTER WATER LLC Resp Co

Well Name: HELEN F HALL (SWIW #7) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Producers Services on site to perform 2000 acid treatment on said well they pumped 1000 gallon of acid and displaced it into formation and let soak for one hour and then pumped remaining 1000 gallon and displaced it into formation again and let soak for one additional hour before placing well back into operation.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: 400 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/20/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed: 3/20/2015

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

10/24/2014 Operator changed from 7434, VIRCO INC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that owner has moved three dozers on site to start building location and they plan on moving drilling rig in on site within the next three weeks.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/23/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL CO 1 LLC Resp Co

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness mini test on annulus of injection string they pressured up to 680 psi and we monitored pressure for 15 minutes with no decline in pressure and it appears that well is not used much at this time due to high pressure issues.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1960 Vac ANNULUSPRESSURE: 680 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/18/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Work Over Reconditioning Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact ERIC CONRAD

Inspection Comments:

I am onsite with Inspector Dave Ball to cross train in the area of injection well control. The service rig crew is running 2.875" tubing with a Baker A three set lock packer.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/23/2015

Signature: _____
ERIC CONRAD

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Production Wells Contact: Phone
Inspection Purpose: Status Check Address
Type of Notification Contact ERIC CONRAD

Inspection Comments:

My inspection today finds the Haught Well Service rig is running 2.875" tubing in the well with a Baker A 3 set lock packer.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/17/2015

Signature: _____
ERIC CONRAD

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Production Wells Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness MIT TEST Universal well services pressured up to 1515 psi and we monitored pressure for 15 minutes with minimal leak off (suspect trapped air within fluid column) passed testing requirements.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/31/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Production Wells Contact: Phone
Address

Inspection Purpose: Status Check

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness tubing and packer run into well.
New 2.875" tubing and Baker A-3 set lock packer with on/off tool.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/30/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH
WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Production Wells Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness small 500 gal acid treatment on well to determine if it would possibly be a candidate well for injection purposes.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/25/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167293950000

Project: SWIW-6-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL CO 1 LLC Resp Co

Well Name: OHIO OIL GATHERING CORP II (S No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation on the day of my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1895 Vac ANNULUSPRESSURE: 600 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/13/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner APPALACHIAN OIL PURCHASERS INC

Former Owners

7/6/2001 Operator changed from 6357, APPALACHIAN OIL PURCHASERS INC to 2153, OOGC DISPOSAL CO #1

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL CO 1 LLC Resp Co

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that well is not used much at this time.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1900 Vac ANNULUSPRESSURE: 590 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/13/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296850000

Project: SWIW-10-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL CO 1 LLC Resp Co

Well Name: NEWELL RUN DISPOSAL WELL(S) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1935 Vac ANNULUSPRESSURE: 80 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/13/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296580000

Project: SWIW-8-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL CO 1 LLC Resp Co

Well Name: LONG RUN DISPOSAL WELL(SWI No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation on the day of my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1860 Vac ANNULUSPRESSURE: 130 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/13/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection on this day indicated that injection pump was in operation and it was noted that two 25-361 vacuum trucks were unloading at the facility on this day.

Note: Crew was working on concrete entrance way off of state route 339 on this day they currently have half of the driveway entrance completed at this time.

Accompanied by _____

INJECTIONPRESSUR 360 Vac ANNULUSPRESSURE: 680 Vac FLOWMETER: Vac

HAULERNO: 25361 LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/18/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed: 8/18/2015

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection on this day indicated that injection pumps were in operation and I inspected recently built storage tank with open top and secondary containment has been constructed and looks good.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 470 Vac ANNULUSPRESSURE: 320 Vac FLOWMETER: 60956 Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/17/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed: 8/17/2015

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation today and it was noted that one H&L Oilfield services tanker was unloading at the facility during my inspection.

Note: Walked flow line to check area for any potential leaks none were found.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 900 Vac ANNULUSPRESSURE: 205 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/18/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed: 8/18/2015

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was not in operation during my inspection and it was noted that one company owned tanker was unloading at the facility at the time of my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 520 Vac ANNULUSPRESSURE: 850 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/18/2015

Signature:

Date Compliance Issued:

DAVID BALL

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed: 8/18/2015

Duration: _____

hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295770000

Project: SWIW-7-WASH

County: WASHINGTON Twp. LAWRENCE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: GREEN HUNTER WATER LLC Resp Co

Well Name: HELEN F HALL (SWIW #7) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Brine Hauler Contact: Phone

Address

Inspection Purpose: Administrative Inspection

Type of Notification Field Visit or Inspection Contact JENNIFER MICHAEL

Inspection Comments:

On site with UIC Inspector Dave Ball, 1 Brine Truck on site. GreenHunter Water LLC (UIC #25-463) Labeled properly and approved to haul to the Helen Hall well.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/3/2015

Signature:

Date Compliance Issued:

JENNIFER MICHAEL

Required action to be completed by:

Reviewed by:

Extended action completed:

Forward to:

Required action completed: 4/3/2015

Duration: _____ hrs

Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

10/24/2014 Operator changed from 7434, VIRCO INC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection and it was noted that two company owned vacuum trucks were unloading at the facility during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1000 Vac ANNULUSPRESSURE: 800 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/3/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167274010000

Project: SWIW-2-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness MIT Testing of annulus of tubing and ensuring that they have good casing integrity company rep applied 585 psi of pressure and we monitored pressure for 15 minutes with no decline in pressures.(TEST PASSED)

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 390 Vac ANNULUSPRESSURE: 585 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/29/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed: 5/29/2015

Duration: _____ hrs Section/Name

Original Owner BIG INJUN OIL & GAS INC.

Former Owners

12/30/1982 118 BIG INJUN OIL & GAS INC GeoDate 12/30/82

12/13/1984 642 LOTHES OIL & GAS INC GeoDate 12/13/84

5/3/1989 3133 PETROEL GeoDate 5/3/89

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167279580000

Project: SWIW-9-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN(SWIW#9) No.: 3 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness MIT Testing of annulus of tubing and ensuring that they have good casing integrity company rep applied 585 psi of pressure and we monitored pressure for 15 minutes with no decline in pressures.(TEST PASSED)

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 390 Vac ANNULUSPRESSURE: 585 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/29/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed: 5/29/2015

Duration: _____ hrs Section/Name

Original Owner CARPER WELL SERVICE

Former Owners

12/20/1984 3133 PETROEL GeoDate 12/20/84

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: BROAD STREET SERV LLC Resp Co

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection on this day revealed that injection pump was in operation and it was noted that lease road to wellhead has been repaired as requested in previous inspections.

Note: Two H&L Water services vacuum trucks were unloading at the facility during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 900 Vac ANNULUSPRESSURE: 200 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/3/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167293950000

Project: SWIW-6-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL CO 1 LLC Resp Co

Well Name: OHIO OIL GATHERING CORP II (S No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation today and there was crew on site working in the storage tank area.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1880 Vac ANNULUSPRESSURE: 560 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/8/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner APPALACHIAN OIL PURCHASERS INC

Former Owners

7/6/2001 Operator changed from 6357, APPALACHIAN OIL PURCHASERS INC to 2153, OOGC DISPOSAL CO #1

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296180000

Project: SWIW-15-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: GREEN HUNTER WATER LLC Resp Co

Well Name: GREENWOOD UNIT (SWIW #15) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Well is not in operation at this time owner is waiting on plug back permit to be issued.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1550 Vac ANNULUSPRESSURE: 1550 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/8/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

3/24/2010 Operator changed from 2348, TRIAD RESOURCES INC to 8610, TRIAD HUNTER LLC

12/21/2011 Operator changed from 8610, TRIAD HUNTER LLC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295770000

Project: SWIW-7-WASH

County: WASHINGTON Twp. LAWRENCE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: GREEN HUNTER WATER LLC Resp Co

Well Name: HELEN F HALL (SWIW #7) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness operator replace vault for unloading/dike drains they remove old plastic type vault and replaced it with a heavy duty concrete one with the capacity of 1000 gallon.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1250 Vac ANNULUSPRESSURE: 400 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/3/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

10/24/2014 Operator changed from 7434, VIRCO INC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to pressure test new flow line for temporary injection facility we tested the 2" flow line too 1600 psi and monitored pressure for 15 minutes with no decline in pressure and owner plans on starting 48 hour injection test tomorrow.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: 500 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/2/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL CO 1 LLC Resp Co

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that well is in operation but it appears that it is not used much at this time.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1900 Vac ANNULUSPRESSURE: 600 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/8/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296580000

Project: SWIW-8-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL CO 1 LLC Resp Co

Well Name: LONG RUN DISPOSAL WELL(SWI No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that well was in operation during my inspection and it was noted that 1/4" valves on annulus of tubing has been replaced since my last inspection.

Note: Creek crossing will need repaired in the near future.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1675 Vac ANNULUSPRESSURE: 580 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/8/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296850000

Project: SWIW-10-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL CO 1 LLC Resp Co

Well Name: NEWELL RUN DISPOSAL WELL(S) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that well was in operation during my inspection and it was noted that 1/4" valve on annulus of tubing has been replaced since my last inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1940 Vac ANNULUSPRESSURE: 350 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/8/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection on this day revealed that well is not in operation at this time owner has submitted plans for a temporary operating facility while permanent facility is constructed and plan is under review by the divisions legal team.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/3/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness owner put scale inhibitor and bacteria side in well too help prevent any build up of bacteria in well bore while they are waiting on permission to inject fluid.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: 900 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/23/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness MIT test on said well they pressured up to 1500 psi and we monitored pressure for 20 minutes with no decline in pressures (TEST PASSED).

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 0 Vac ANNULUSPRESSURE: 1500 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/23/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: BROAD STREET SERV LLC Resp Co

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation today and containment volumes are as follows it is 40'x82'x44" high with 14-210 bbl connected at the bottom and 1-100 bbl oil tank, and there is also additional capacity available 50'x12'x48" there is no tanks within this area.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 970 Vac ANNULUSPRESSURE: 200 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/1/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167279580000

Project: SWIW-9-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN(SWIW#9) No.: 3 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection and we measured dike area and recorded total amount of tanks with in dike area.
61'x40'x48" high with a calculated volume of 1733 bbl and there is 5-210 bbl placed within dike area.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 370 Vac ANNULUSPRESSURE: 530 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/1/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner CARPER WELL SERVICE

Former Owners

12/20/1984 3133 PETROEL GeoDate 12/20/84

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167274010000

Project: SWIW-2-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection and we measured dike area and recorded total amount of tanks with in dike area.
61'x40'x48" high with a calculated volume of 1733 bbl and there is 5-210 bbl placed within dike area.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 370 Vac ANNULUSPRESSURE: 530 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/1/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner BIG INJUN OIL & GAS INC.

Former Owners

12/30/1982 118 BIG INJUN OIL & GAS INC GeoDate 12/30/82

12/13/1984 642 LOTHES OIL & GAS INC GeoDate 12/13/84

5/3/1989 3133 PETROEL GeoDate 5/3/89

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness contractor play spray on sealant on seams of containment area and operator is hoping to get approval to spray the entire area within dike in the near future.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 920 Vac ANNULUSPRESSURE: 850 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/8/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation today and containment volumes are as follows 80'x50'x36" high with a calculated total of 2132 bbl and dike has 6-400 bbl tanks within it with 5 connected at the bottom and one is used for oil tank.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 970 Vac ANNULUSPRESSURE: 800 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/1/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation today and it was noted that six AOS vacuum trucks were waiting to unload at the facility on this day of my inspection.

Note: Witnessed containment put in place at the site of the permanent tank storage site and according to owner they will start tank construction later on in the week.

Accompanied by _____

INJECTIONPRESSUR 800 Vac ANNULUSPRESSURE: 480 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/20/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to confirm that owner has installed Murphy Switch on said well and they have completed required task and they are waiting on Chiefs Order to operate said well at this point in time.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/17/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to pressure test flow line to well, we tested 2" line too 1640 psi with no decline in pressure during the 15 min. test period.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/13/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Brine Hauler Contact: Phone

Inspection Purpose: Administrative Inspection Address

Type of Notification Field Visit or Inspection Contact JENNIFER MICHAEL

Inspection Comments:

PERFORMED FIELD AUDIT OF BRINE TRUCKS:(1) SELECT ENERGY SERVICES TRUCK ON SITE LABELED PROPERLY AND APPROVED TO HAUL TO THE NICHOLS #1-A. NO TRUCK VIOLATIONS FOUND.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/1/2015

Signature: _____
JENNIFER MICHAEL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Brine Hauler Contact: Phone

Address

Inspection Purpose: Administrative Inspection

Type of Notification Field Visit or Inspection Contact JENNIFER MICHAEL

Inspection Comments:

PERFORMED FIELD AUDIT OF BRINE TRUCKS: ENERGY TRANSPORTATION LLC UIC #25-601 ON SITE LABELED PROPERLY AND APPROVED TO HAUL TO THE FLOWERS #1 WELL. NO TRUCK VIOLATIONS FOUND.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/3/2015

Signature:

Date Compliance Issued:

JENNIFER MICHAEL

Required action to be completed by:

Reviewed by:

Extended action completed:

Forward to:

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection and it was noted that one 25-534 vacuum truck was unloading at the facility during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 200 Vac ANNULUSPRESSURE: 800 Vac FLOWMETER: 29182 Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/31/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed: 7/31/2015

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection on this day indicated that injection pump was in operation and it was noted that valve on annulus of tubing was froze up and I was unable to check pressure.

Several ECM Trucks were unloading at the state route 7 facility today and one BD Oil Hauling truck also.

Accompanied by _____

INJECTIONPRESSUR 890 Vac ANNULUSPRESSURE: Vac FLOWMETER: 2450 Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/22/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection on this day indicated that injection pump was in operation and it was noted that valve on annulus of tubing was froze up and I was unable to check pressure.

Several ECM Trucks were unloading at the state route 7 facility today and one BD Oil Hauling truck also.

Accompanied by _____

INJECTIONPRESSUR 1020 Vac ANNULUSPRESSURE: Vac FLOWMETER: 131205 Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/22/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC

12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC

12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.

12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC

12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection on this day indicated that injection pump was in operation and it was noted that valve on annulus of tubing was froze up and I was unable to check pressure.

Several ECM Trucks were unloading at the state route 7 facility today and one BD Oil Hauling truck also.

Accompanied by _____

INJECTIONPRESSUR 540 Vac ANNULUSPRESSURE: Vac FLOWMETER: 40229 Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/22/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was not in operation today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 25 Vac ANNULUSPRESSURE: 310 Vac FLOWMETER: 62449 Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/3/2016

Signature: _____

Date Compliance Issued:

DAVID BALL

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 760 Vac ANNULUSPRESSURE: 300 Vac FLOWMETER: 15758 Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/3/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was not in operation during my inspection due to DXP was changing oil in the pump today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 360 Vac ANNULUSPRESSURE: 100 Vac FLOWMETER: 153107 Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/3/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection and it was noted that four AOS vacuum trucks were unloading at the state route seven facility today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/21/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection and it was noted that three Hall Drilling vacuum trucks were unloading at the facility on this day of my inspections.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 750 Vac ANNULUSPRESSURE: 935 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/21/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that well is not used much at this time.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1650 Vac ANNULUSPRESSURE: 1650 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/8/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump was in operation during my inspection and it was noted that fluid level in 23,000 bbl tank was at the ten foot mark.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 960 Vac ANNULUSPRESSURE: 345 Vac FLOWMETER: 83356 Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/5/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295770000

Project: SWIW-7-WASH

County: WASHINGTON Twp. LAWRENCE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: GREEN HUNTER WATER LLC Resp Co

Well Name: HELEN F HALL (SWIW #7) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation today and it was noted that two Green Hunter vacuum trucks were unloading at the facility today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1490 Vac ANNULUSPRESSURE: 210 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/8/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

10/24/2014 Operator changed from 7434, VIRCO INC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump too this well not running today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 30 Vac ANNULUSPRESSURE: 375 Vac FLOWMETER: 16373 Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/5/2016

Signature: _____

Date Compliance Issued: _____

DAVID BALL

Required action to be completed by: _____

Reviewed by: _____

Extended action completed: _____

Forward to: _____

Required action completed: _____

Duration: _____

hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump too this well not running today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 0 Vac ANNULUSPRESSURE: 500 Vac FLOWMETER: 63 Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/5/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation today and it was noted that lease road to wellhead will need to be smoothed up come spring.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 950 Vac ANNULUSPRESSURE: 150 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/5/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection on this day revealed that workers were changing packing in injection pump.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 610 Vac ANNULUSPRESSURE: 390 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/5/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167274010000

Project: SWIW-2-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 180 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/11/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner BIG INJUN OIL & GAS INC.

Former Owners

12/30/1982 118 BIG INJUN OIL & GAS INC GeoDate 12/30/82

12/13/1984 642 LOTHES OIL & GAS INC GeoDate 12/13/84

5/3/1989 3133 PETROEL GeoDate 5/3/89

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167279580000

Project: SWIW-9-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN(SWIW#9) No.: 3 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 175 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/11/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner CARPER WELL SERVICE

Former Owners

12/20/1984 3133 PETROEL GeoDate 12/20/84

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296180000

Project: SWIW-15-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: GREEN HUNTER WATER LLC Resp Co

Well Name: GREENWOOD UNIT (SWIW #15) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Waiting on owner to repair/plug back well to a formation that will take fluids.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1250 Vac ANNULUSPRESSURE: 1250 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/8/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

3/24/2010 Operator changed from 2348, TRIAD RESOURCES INC to 8610, TRIAD HUNTER LLC

12/21/2011 Operator changed from 8610, TRIAD HUNTER LLC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection on this day indicated that injection pump was in operation and it was noted that one Hall Drilling tanker was unloading at the facility during my inspection.

Note: Permanent facility construction has not begun as of this date.

Accompanied by _____

INJECTIONPRESSUR 410 Vac ANNULUSPRESSURE: 720 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/11/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Pump not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 0 Vac ANNULUSPRESSURE: 820 Vac FLOWMETER: 242643 Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/29/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation and it was noted that there was no activity at the unloading site during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 950 Vac ANNULUSPRESSURE: 300 Vac FLOWMETER: 116491 Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/29/2016

Signature:

Date Compliance Issued:

DAVID BALL

Required action to be completed by:

Reviewed by:

Extended action completed:

Forward to:

Required action completed:

Duration: _____ hrs

Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation and it was noted that there was no activity at the unloading site during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 950 Vac ANNULUSPRESSURE: 280 Vac FLOWMETER: 79554 Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/29/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Permanent facility under construction and it was noted that injection pump was in operation today and there was three Hall Drilling vacuum trucks unloading at the facility today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 975 Vac ANNULUSPRESSURE: 1030 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/29/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was not in operation during my inspection and it was noted that one company owned tanker truck was unloading at the facility during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 40 Vac ANNULUSPRESSURE: 650 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/26/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump was in operation today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 960 Vac ANNULUSPRESSURE: 310 Vac FLOWMETER: 62032 Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/26/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump was in operation today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1020 Vac ANNULUSPRESSURE: 300 Vac FLOWMETER: 114213 Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/26/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump was in operation today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 940 Vac ANNULUSPRESSURE: 100 Vac FLOWMETER: 205774 Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/26/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump was in operation today and owner wants to set up meeting to discuss plans for further development at the site.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 910 Vac ANNULUSPRESSURE: 1000 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/26/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Unable to check pressures today due to locks being changed out at the well head, called company and requested key so I can get required pressure readings.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/1/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296850000

Project: SWIW-10-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: NEWELL RUN DISPOSAL WELL(S) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump was in operation today and it was noted that creek crossing culverts are partially plugged up and I made company aware of the problem.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1945 Vac ANNULUSPRESSURE: 250 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/1/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296580000

Project: SWIW-8-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: LONG RUN DISPOSAL WELL(SWI No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Address

Inspection Purpose: Status Check

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump was in operation today.

Note: Two pen recorder needs to be recalibrated.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1710 Vac ANNULUSPRESSURE: 220 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/1/2016

Signature:

Date Compliance Issued:

DAVID BALL

Required action to be completed by:

Reviewed by:

Extended action completed:

Forward to:

Required action completed:

Duration: _____ hrs

Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295770000

Project: SWIW-7-WASH

County: WASHINGTON Twp. LAWRENCE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: GREEN HUNTER WATER LLC Resp Co

Well Name: HELEN F HALL (SWIW #7) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation and it was noted that one company owned tanker truck was unloading at the facility during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1800 Vac ANNULUSPRESSURE: 130 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/1/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

10/24/2014 Operator changed from 7434, VIRCO INC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296180000

Project: SWIW-15-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: GREEN HUNTER WATER LLC Resp Co

Well Name: GREENWOOD UNIT (SWIW #15) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that well is still down for repair and I was unable o check annulus pressure due to bad two inch valve of well head.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1250 Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/1/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

3/24/2010 Operator changed from 2348, TRIAD RESOURCES INC to 8610, TRIAD HUNTER LLC

12/21/2011 Operator changed from 8610, TRIAD HUNTER LLC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167293950000

Project: SWIW-6-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: OHIO OIL GATHERING CORP II (S No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump was in operation today.

Note: Two pen recorder needs to be recalibrated.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1860 Vac ANNULUSPRESSURE: 300 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/1/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner APPALACHIAN OIL PURCHASERS INC

Former Owners

7/6/2001 Operator changed from 6357, APPALACHIAN OIL PURCHASERS INC to 2153, OOGC DISPOSAL CO #1

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation and it was noted that two J&L Water Services vacuum trucks were pulling from site upon my arrival at the site.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1050 Vac ANNULUSPRESSURE: 180 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/4/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295770000

Project: SWIW-7-WASH

County: WASHINGTON Twp. LAWRENCE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: GREEN HUNTER WATER LLC Resp Co

Well Name: HELEN F HALL (SWIW #7) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Baker-Hughes on site to perform chemical treatment on said well.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1790 Vac ANNULUSPRESSURE: 140 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/14/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

10/24/2014 Operator changed from 7434, VIRCO INC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that Producers Services was on site to perform 2500 gallon acid treatment on said well(28%).

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 920 Vac ANNULUSPRESSURE: 1010 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/9/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Casing String Witnessed Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact ERIC CONRAD

Inspection Comments:

I am onsite to witness the 5.5" casing installation and cementing operations. Decker Rig 8 ran 5733' of 5.5" casing. The casing string sat down early so Appalachian Well Survey was brought to location to confirm the depth of the casing string and the open hole plug. Appalachian found the bottom of the casing string was at 5734' setting on the plug. The plug depth was determined to be at 5734' after correlating the gamma ray log. Baker Hughes cemented the casing in place with 160 barrels of class A cement and additives. The plug landed 145' early based on displacement calculations.

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/5/2015

Signature: _____
ERIC CONRAD

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295770000

Project: SWIW-7-WASH

County: WASHINGTON Twp. LAWRENCE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: GREEN HUNTER WATER LLC Resp Co

Well Name: HELEN F HALL (SWIW #7) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation today and it was noted that one company owned vacuum truck was unloading at the site during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1220 Vac ANNULUSPRESSURE: 390 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/3/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

10/24/2014 Operator changed from 7434, VIRCO INC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296180000

Project: SWIW-15-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: GREEN HUNTER WATER LLC Resp Co

Well Name: GREENWOOD UNIT (SWIW #15) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to perform site review for possible plug back operation in the near future once permit is issued.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/10/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

3/24/2010 Operator changed from 2348, TRIAD RESOURCES INC to 8610, TRIAD HUNTER LLC

12/21/2011 Operator changed from 8610, TRIAD HUNTER LLC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness tubing and packer run into well and witness MIT test of annulus of tubing.
Note: Center of element on packer is at 5516' and tubing string was 2.875" lined tubing and top perforation was noted at 5542'. Baker A-2 LOCK SET PACKER SET IN 20,000 COMPRESSION.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: 1345 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/14/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that Baker-Hughes was on site to perform acid treatment on well and also perform small flow test, they pumped 1500 gallon of 28% acid and formation broke down at 1220 psi and they pumped at a rate of 5.2 barrel per minute with zero pressure well was on vacuum.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/12/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness bond logging of well and Appalachian Well Services also perforated casing in the Clinton/Medina sandstone.

Note: Top perf at 5542' and bottom perf at 5708' there is 100 shots recorded on copy of log.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/10/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Casing String Witnessed Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Decker Drilling running and cementing production casing in place they ran 5735' of new 5.5" casing. Estimated cement top@1078' will confirm on Friday with bond log.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/5/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Drill / Deepen / Reopen Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Decker Drilling was dusting in the shale at 2700' on this day of my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/1/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Drill / Deepen / Reopen Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Decker Drilling rigging up today and digging pit and line it and they will start drilling surface hole later this afternoon.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/27/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site: 339 south to Veto location on the right side of road

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection on this day determined that owner was digging pit and they are planning on drilling surface hole beginning on 4/26/15.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/22/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site: 339 south of Veto on the right.

Inspection Type: Casing String Witnessed Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness running and cementing of conductor pipe, Ransom Drilling was contractor they ran 60' of 20" casing and cemented it in place with seven yards of nine sack grout. Note: Spud date was 4/6/15.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/7/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Owner building location and conductor rig should be moving in next week.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/1/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to pressure test new 3" steel flow line coming from new pump house to wellhead we pressure tested line at 1600 psi with no pressure loss during test period and they we proceeded to inspect new 24,000 bbl. Tank and all connections going to pump house and returning to wellhead no leaks were found at this time.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 700 Vac ANNULUSPRESSURE: 320 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/25/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed: 9/25/2015

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site: 676 behind Career center

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection on this day indicated that injection pumps were in operation and it was noted that one AOS vacuum truck was unloading at the facility during my inspection.

Note: Owner has installed a 24,000 bbl. storage tank at site and the containment area for tank is as follows 206'L & 131'W & 72" high.

Accompanied by _____

INJECTIONPRESSUR 600 Vac ANNULUSPRESSURE: 320 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/10/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed: 9/10/2015

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness owner pressure test new fiber spar flow line we step rested flow line to 1175 psi and monitored pressure for 20 minutes with no decline in pressure and old flow line was flushed with fresh water prior to being taken out of service.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/1/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed: 9/1/2015

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 970 Vac ANNULUSPRESSURE: 300 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/29/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 950 Vac ANNULUSPRESSURE: 310 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/29/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 965 Vac ANNULUSPRESSURE: 400 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/29/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pumps were not in operation during my inspection and it was noted that six Hall Drilling vacuum trucks were unloading at the facility during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 640 Vac ANNULUSPRESSURE: 960 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/6/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296580000

Project: SWIW-8-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: LONG RUN DISPOSAL WELL(SWI No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump too this well was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1560 Vac ANNULUSPRESSURE: 590 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/6/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296850000

Project: SWIW-10-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: NEWELL RUN DISPOSAL WELL(S) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump too this well was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1920 Vac ANNULUSPRESSURE: 210 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/6/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167293950000

Project: SWIW-6-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: OHIO OIL GATHERING CORP II (S No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump too this well was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1880 Vac ANNULUSPRESSURE: 550 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/6/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner APPALACHIAN OIL PURCHASERS INC

Former Owners

7/6/2001 Operator changed from 6357, APPALACHIAN OIL PURCHASERS INC to 2153, OOGC DISPOSAL CO #1

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation today and I walked flow line area to monitor area for any potential leaks none were found and I.D. was posted at wellhead and tank area respectively.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1000 Vac ANNULUSPRESSURE: 180 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/6/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167279580000

Project: SWIW-9-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN(SWIW#9) No.: 3 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was not in operation and it was noted that injection line right away has been recently brush hogged and there was a worker on site weed eating around containment area during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 180 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/6/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner CARPER WELL SERVICE

Former Owners

12/20/1984 3133 PETROEL GeoDate 12/20/84

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Well is down due to lack of water for disposal use.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 35 Vac ANNULUSPRESSURE: 550 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/6/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167274010000

Project: SWIW-2-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was not in operation and it was noted that injection line right away has been recently brush hogged and there was a worker on site weed eating around containment area during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 195 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/6/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner BIG INJUN OIL & GAS INC.

Former Owners

12/30/1982 118 BIG INJUN OIL & GAS INC GeoDate 12/30/82

12/13/1984 642 LOTHES OIL & GAS INC GeoDate 12/13/84

5/3/1989 3133 PETROEL GeoDate 5/3/89

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296850000

Project: SWIW-10-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: NEWELL RUN DISPOSAL WELL(S) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump to this well was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1860 Vac ANNULUSPRESSURE: 260 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/14/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295770000

Project: SWIW-7-WASH

County: WASHINGTON Twp. LAWRENCE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: FQ ENERGY SERVICES LLC Resp Co

Well Name: HELEN F HALL (SWIW #7) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation during my inspection and it was noted that two GreenHunter vacuum trucks were unloading at the facility today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1760 Vac ANNULUSPRESSURE: 60 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/14/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

10/24/2014 Operator changed from 7434, VIRCO INC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump not in operation during my inspection and it was noted that electrical worker was on site replacing barrel counters for said wells being operated out of this facility.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1000 Vac ANNULUSPRESSURE: 440 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/22/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump not in operation during my inspection and it was noted that electrical worker was on site replacing barrel counters for said wells being operated out of this facility.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1000 Vac ANNULUSPRESSURE: 580 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/22/2016

Signature:

Date Compliance Issued:

DAVID BALL

Required action to be completed by:

Reviewed by:

Extended action completed:

Forward to:

Required action completed:

Duration: _____ hrs

Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump not in operation during my inspection and it was noted that electrical worker was on site replacing barrel counters for said wells being operated out of this facility.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1000 Vac ANNULUSPRESSURE: 580 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/22/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump not in operation during my inspection and it was noted that electrical worker was on site replacing barrel counters for said wells being operated out of this facility.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 940 Vac ANNULUSPRESSURE: 420 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/22/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection on this day revealed that injection pump was not in operation and it was noted that electric company was on site at the pump house making upgrades to electrical service.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 280 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/19/2016

Signature: _____

Date Compliance Issued:

DAVID BALL

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection on this day revealed that injection pump was not in operation and it was noted that electric company was on site at the pump house making upgrades to electrical service.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 400 Vac ANNULUSPRESSURE: 680 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/19/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 300 Vac ANNULUSPRESSURE: 430 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/19/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295770000

Project: SWIW-7-WASH

County: WASHINGTON Twp. LAWRENCE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: GREEN HUNTER WATER LLC Resp Co

Well Name: HELEN F HALL (SWIW #7) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation and it was noted that three company owned vacuum trucks were at the facility during my inspection and I discussed with operator that the liner in the containment area needs to have stone reapplied to bare spots on it too help protect it from the sunlight.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1800 Vac ANNULUSPRESSURE: 130 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/29/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

10/24/2014 Operator changed from 7434, VIRCO INC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167293950000

Project: SWIW-6-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: OHIO OIL GATHERING CORP II (S No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump too this well was in operation today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1860 Vac ANNULUSPRESSURE: 560 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/26/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner APPALACHIAN OIL PURCHASERS INC

Former Owners

7/6/2001 Operator changed from 6357, APPALACHIAN OIL PURCHASERS INC to 2153, OOGC DISPOSAL CO #1

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump too this well was in operation today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1800 Vac ANNULUSPRESSURE: 550 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/26/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that new injection pump in permanent facility was in operation and it was noted that six Hall Drilling vacuum trucks were unloading at the facility during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1250 Vac ANNULUSPRESSURE: 100 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/26/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness 3000 gallon acid treatment on well, Producers Services performed job and owner is currently operating off of the permanent facility and the temporarily facility is being decommissioned.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/10/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296850000

Project: SWIW-10-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: NEWELL RUN DISPOSAL WELL(S) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump to this well was in operation today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1910 Vac ANNULUSPRESSURE: 235 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/26/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296580000

Project: SWIW-8-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: LONG RUN DISPOSAL WELL(SWI No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump to this well was in operation today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1600 Vac ANNULUSPRESSURE: 600 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/26/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295770000

Project: SWIW-7-WASH

County: WASHINGTON Twp. LAWRENCE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: FQ ENERGY SERVICES LLC Resp Co

Well Name: HELEN F HALL (SWIW #7) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation and it was noted that roll off box with the old filters has been removed from site.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1800 Vac ANNULUSPRESSURE: 200 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/26/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

10/24/2014 Operator changed from 7434, VIRCO INC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to pressure test flow line at the state route seven facility the 4" flow line was tested at 500 psi and pressure monitored for 20 minutes with no decline in pressure Universal Well Services performed pumping of fresh water and pressure testing.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/30/2015

Signature:

Date Compliance Issued:

DAVID BALL

Required action to be completed by:

Reviewed by:

Extended action completed:

Forward to:

Required action completed: 11/30/2015

Duration: _____

hrs

Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to pressure test flow line at the state route seven facility the 4" flow line was tested at 500 psi and pressure monitored for 20 minutes with no decline in pressure Universal Well Services performed pumping of fresh water and pressure testing.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/30/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed: 11/30/2015

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to pressure test flow line at the state route seven facility the 4" flow line was tested at 500 psi and pressure monitored for 20 minutes with no decline in pressure Universal Well Services performed pumping of fresh water and pressure testing.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/30/2015

Signature:

Date Compliance Issued:

DAVID BALL

Required action to be completed by:

Reviewed by:

Extended action completed:

Forward to:

Required action completed: 11/30/2015

Duration: _____

hrs

Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection on this day indicated that injection pump was in operation and owner is currently using 24,000 bbl. Tank for storage.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 800 Vac ANNULUSPRESSURE: 480 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/1/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection on this day indicated that injection pump was in operation and it was noted that four Hall Drilling vacuum trucks were waiting to unload during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 800 Vac ANNULUSPRESSURE: 1120 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/1/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation and a land owner 5.2 mile away thinks well is affecting his wellhead pressure the well in question was noted as the Hathaway lease permit number 9099.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 560 Vac ANNULUSPRESSURE: 1100 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/19/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness Producers Services perform 1500 gallon acid treatment on said well.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/10/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation today and it was noted that new 3" flow line was being installed to two other wells involved in this project Heinrich#1 there is a 6" outer pipe and 3" flex steel line inserted within the outer pipe.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 750 Vac ANNULUSPRESSURE: 320 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/10/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness MIT testing and pressure testing of flowline to wellhead.
MIT test passed@1540 psi.
Flowline test@1500 psi with no decline in pressure.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: 1540 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/16/2015

Signature:

Date Compliance Issued:

DAVID BALL

Required action to be completed by:

Reviewed by:

Extended action completed:

Forward to:

Required action completed: 11/16/2015

Duration: _____ hrs

Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH
WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation today and I walked flow line to monitor area for and potential leakage none was found and it was noted that two 25-601 transports were unloading at the facility during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1050 Vac ANNULUSPRESSURE: 200 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/10/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection and it was noted that four company owned vacuum trucks were unloading at the facility on this day of my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 830 Vac ANNULUSPRESSURE: 550 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/10/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167274010000

Project: SWIW-2-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was not in operation today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 160 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/17/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner BIG INJUN OIL & GAS INC.

Former Owners

12/30/1982 118 BIG INJUN OIL & GAS INC GeoDate 12/30/82

12/13/1984 642 LOTHES OIL & GAS INC GeoDate 12/13/84

5/3/1989 3133 PETROEL GeoDate 5/3/89

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167279580000

Project: SWIW-9-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN(SWIW#9) No.: 3 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was not in operation today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 160 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/17/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner CARPER WELL SERVICE

Former Owners

12/20/1984 3133 PETROEL GeoDate 12/20/84

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone
Address

Inspection Purpose: Status Check

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness pressure testing of 4" flow line going from the Rt. 7 facility to the facility up on the state route 676 site, Universal Well services had pump truck on site to pump fresh water and pressure test line after pumping line capacity it was discovered that there was a leak up on the hill caused by equipment crossing line on the right of way they will replace faulty line and retest next week.

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/20/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness MIT testing and pressure testing of flowline to wellhead.
MIT test passed@1520 psi.
Flowline test@1500 psi with no decline in pressure.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: 1520 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/16/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed: 11/16/2015

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation today and it was noted that two Hall Drilling vacuum trucks were unloading at the facility during our inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 875 Vac ANNULUSPRESSURE: 950 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/17/2015

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167293950000

Project: SWIW-6-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: OHIO OIL GATHERING CORP II (S No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness Baker Hughes perform 1500 gallon acid treatment on said well.
Note: 28% HCL acid was used and ISIP was noted at 1767 psi and 30 minute pressure reading was noted at 1723 psi.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/25/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner APPALACHIAN OIL PURCHASERS INC

Former Owners

7/6/2001 Operator changed from 6357, APPALACHIAN OIL PURCHASERS INC to 2153, OOGC DISPOSAL CO #1

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296850000

Project: SWIW-10-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: NEWELL RUN DISPOSAL WELL(S) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness Baker Hughes perform 1500 gallon of 28% acid treatment on said well.
Note: 1932psi was ISIP AND 15 MINUTE READING WAS 1792 PSI AND STILL FALLING OFF.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/25/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295770000

Project: SWIW-7-WASH

County: WASHINGTON Twp. LAWRENCE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: FQ ENERGY SERVICES LLC Resp Co

Well Name: HELEN F HALL (SWIW #7) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation prior to Baker Hughes performing acid treatment job on said well.

Note: Four Green Hunter tanker trucks were unloading at the facility during my time on site.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1800 Vac ANNULUSPRESSURE: 150 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/2/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

10/24/2014 Operator changed from 7434, VIRCO INC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296580000

Project: SWIW-8-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: LONG RUN DISPOSAL WELL(SWI No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump to this well was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1580 Vac ANNULUSPRESSURE: 560 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/6/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Well not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1850 Vac ANNULUSPRESSURE: 560 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/6/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was not operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 440 Vac ANNULUSPRESSURE: 510 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/14/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection and I walked flow line area to monitor area for any noticeable leaks none were detected.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 960 Vac ANNULUSPRESSURE: 560 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/14/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection and I walked flow line area to monitor area for any noticeable leaks none were detected.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 920 Vac ANNULUSPRESSURE: 540 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/14/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation and I walked flow line area to monitor for potential leaks none were found and it was noted that two 25-601 brine hauler was unloading at the facility during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 750 Vac ANNULUSPRESSURE: 200 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/14/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 140 Vac ANNULUSPRESSURE: 380 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/14/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation and it was noted that construction of permanent facility is nearly complete, told operator that we would be required to test new flow line before placing it in use.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1240 Vac ANNULUSPRESSURE: 500 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/14/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump was not in operation during my inspection.
Note: Housekeeping needed in storage tank area.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 110 Vac ANNULUSPRESSURE: 545 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/4/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 900 Vac ANNULUSPRESSURE: 180 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/4/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that four Hall Drilling vacuum trucks were unloading at the facility during my inspection and it was noted that work still continues on permanent facility construction.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1200 Vac ANNULUSPRESSURE: 850 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/4/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that work still continues of facility construction and it was noted that six Hall Drilling vacuum trucks were unloading at the facility during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1240 Vac ANNULUSPRESSURE: 960 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/19/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation.

Note: Visit to route seven facility revealed that owner was in process of correcting slip area behind tank containment area.

Accompanied by _____

INJECTIONPRESSUR 960 Vac ANNULUSPRESSURE: 340 Vac FLOWMETER: 334013 Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/19/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation.

Note: Visit to route seven facility revealed that owner was in process of correcting slip area behind tank containment area.

Accompanied by _____

INJECTIONPRESSUR 960 Vac ANNULUSPRESSURE: 280 Vac FLOWMETER: 279297 Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/19/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump to this well was not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 0 Vac ANNULUSPRESSURE: 300 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/19/2016

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167293950000

Project: SWIW-6-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: OHIO OIL GATHERING CORP II (S No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump to this well was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1875 Vac ANNULUSPRESSURE: 320 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/1/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner APPALACHIAN OIL PURCHASERS INC

Former Owners

7/6/2001 Operator changed from 6357, APPALACHIAN OIL PURCHASERS INC to 2153, OOGC DISPOSAL CO #1

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296180000

Project: SWIW-15-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: FQ ENERGY SERVICES LLC Resp Co

Well Name: GREENWOOD UNIT (SWIW #15) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that well is still down waiting on service rig to plug said well, according to company rep Dave Casto they are planning on plugging well in March 2017 we received document from company rep stating that well would be plugged at that time frame
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/1/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

3/24/2010 Operator changed from 2348, TRIAD RESOURCES INC to 8610, TRIAD HUNTER LLC

12/21/2011 Operator changed from 8610, TRIAD HUNTER LLC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295770000

Project: SWIW-7-WASH

County: WASHINGTON Twp. LAWRENCE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: FQ ENERGY SERVICES LLC Resp Co

Well Name: HELEN F HALL (SWIW #7) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation and dike area was clear of fluid and it was noted that one company owned vacuum truck was unloading at the facility during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1820 Vac ANNULUSPRESSURE: 80 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/2/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

10/24/2014 Operator changed from 7434, VIRCO INC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that well was not in operation during my inspection and currently owner is not using well much because of high pressure issues, injection zones in this area are tight Clinton/Medina.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1800 Vac ANNULUSPRESSURE: 300 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/1/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296580000

Project: SWIW-8-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: LONG RUN DISPOSAL WELL(SWI No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump to this well was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1620 Vac ANNULUSPRESSURE: 480 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/1/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296850000

Project: SWIW-10-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: NEWELL RUN DISPOSAL WELL(S) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump to this well was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1880 Vac ANNULUSPRESSURE: 245 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/1/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation today and it was noted three CJ Trucking tankers were on site unloading during my inspection.

Note: Bob Lane construction company has moved in on site with equipment to widen out entrance to facility.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1120 Vac ANNULUSPRESSURE: 360 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/13/2017

Signature: _____

Date Compliance Issued: _____

DAVID BALL

Required action to be completed by: _____

Reviewed by: _____

Extended action completed: _____

Forward to: _____

Required action completed: _____

Duration: _____ hrs

Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC

12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC

12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.

12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC

12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167274010000

Project: SWIW-2-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that well is not in operation at this time but I had owner come out and perform mini pressure test on annulus of tubing to ensure the division of casing integrity.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 0 Vac ANNULUSPRESSURE: 210 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/8/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner BIG INJUN OIL & GAS INC.

Former Owners

12/30/1982 118 BIG INJUN OIL & GAS INC GeoDate 12/30/82

12/13/1984 642 LOTHES OIL & GAS INC GeoDate 12/13/84

5/3/1989 3133 PETROEL GeoDate 5/3/89

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167279580000

Project: SWIW-9-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN(SWIW#9) No.: 3 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that well is not in operation at this time but I had owner come out and perform mini pressure test on annulus of tubing to ensure the division of casing integrity.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 0 Vac ANNULUSPRESSURE: 200 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/8/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner CARPER WELL SERVICE

Former Owners

12/20/1984 3133 PETROEL GeoDate 12/20/84

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation today and it was noted three CJ Trucking tankers were on site unloading during my inspection.

Note: Bob Lane construction company has moved in on site with equipment to widen out entrance to facility.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1100 Vac ANNULUSPRESSURE: 200 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/13/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC

12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC

12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.

12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC

12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation today and it was noted three CJ Trucking tankers were on site unloading during my inspection.

Note: Bob Lane construction company has moved in on site with equipment to widen out entrance to facility.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1060 Vac ANNULUSPRESSURE: 320 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/13/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump was in operation during my inspection and it was noted that brine hauler 25-544 and two Hall Drilling vacuum trucks were unloading at the facility today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1250 Vac ANNULUSPRESSURE: 80 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/13/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation during my inspection and it was noted that three Hall Drilling tankers were on site during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1270 Vac ANNULUSPRESSURE: 220 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/22/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation and it was noted that one Energy Transport tanker was on site unloading during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 960 Vac ANNULUSPRESSURE: 135 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/22/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Well currently is not in operation due to low brine water intake.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 25 Vac ANNULUSPRESSURE: 180 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/22/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation and I inspected containment wall area that owner wants to install a flex boot at a lower interval and it appears if boot and sealant are applied properly there will be proper sealage of area.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1180 Vac ANNULUSPRESSURE: 300 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/28/2017

Signature: _____

Date Compliance Issued:

DAVID BALL

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC

12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC

12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.

12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC

12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation and I inspected containment wall area that owner wants to install a flex boot at a lower interval and it appears if boot and sealant are applied properly there will be proper sealage of area.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1180 Vac ANNULUSPRESSURE: 740 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/28/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation and I inspected containment wall area that owner wants to install a flex boot at a lower interval and it appears if boot and sealant are applied properly there will be proper sealage of area.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1180 Vac ANNULUSPRESSURE: 480 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/28/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296180000

Project: SWIW-15-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: FQ ENERGY SERVICES LLC Resp Co

Well Name: GREENWOOD UNIT (SWIW #15) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Talked to Brian Haught cocerning upcoming plugging operation on said well.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/21/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

3/24/2010 Operator changed from 2348, TRIAD RESOURCES INC to 8610, TRIAD HUNTER LLC

12/21/2011 Operator changed from 8610, TRIAD HUNTER LLC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296180000

Project: SWIW-15-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: FQ ENERGY SERVICES LLC Resp Co

Well Name: GREENWOOD UNIT (SWIW #15) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness killing of well with 12.5# kill fluid once well became static they released packer and started it out of wellbore they plan on getting packer and tubing out of well tomorrow and then run open ended tubing back into well to a depth of 7350' and then set bottom hole plug.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/27/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

3/24/2010 Operator changed from 2348, TRIAD RESOURCES INC to 8610, TRIAD HUNTER LLC

12/21/2011 Operator changed from 8610, TRIAD HUNTER LLC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296180000

Project: SWIW-15-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: FQ ENERGY SERVICES LLC Resp Co

Well Name: GREENWOOD UNIT (SWIW #15) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness pumping of 12.5# per gallon of kill fluid down well and once well was static they released packer and started to remove tubing and packer from wellbore and they plan on setting bottom hole plug on 3/30/17.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/27/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

3/24/2010 Operator changed from 2348, TRIAD RESOURCES INC to 8610, TRIAD HUNTER LLC

12/21/2011 Operator changed from 8610, TRIAD HUNTER LLC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296180000

Project: SWIW-15-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: FQ ENERGY SERVICES LLC Resp Co

Well Name: GREENWOOD UNIT (SWIW #15) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Pulling tubing and packer they had to kill well again with 12.5# weighted fresh water gel.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/28/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

3/24/2010 Operator changed from 2348, TRIAD RESOURCES INC to 8610, TRIAD HUNTER LLC

12/21/2011 Operator changed from 8610, TRIAD HUNTER LLC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296180000

Project: SWIW-15-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: FQ ENERGY SERVICES LLC Resp Co

Well Name: GREENWOOD UNIT (SWIW #15) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness attempt to set bottom hole plug they were attempting to work string free to possibly set plug but after several attempts to pump tubing free failed decision was made to bring in swivel and rotate pipe to help clean up suspected mud rings within 4.5" casing and once free they will work string back to bottom and set required plug.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/30/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

3/24/2010 Operator changed from 2348, TRIAD RESOURCES INC to 8610, TRIAD HUNTER LLC

12/21/2011 Operator changed from 8610, TRIAD HUNTER LLC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296180000

Project: SWIW-15-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: FQ ENERGY SERVICES LLC Resp Co

Well Name: GREENWOOD UNIT (SWIW #15) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Set bottom hole plug through tubing, had to establish good circulation prior to setting plug suspect weighted kill fluid was causing hole to want to restrict flow once good flow was finally established decision was made to set plug and once displaced locked it into place and operator will cut tubing off 4/3/17 once it is confirmed that cement top is in place.
Note: Formation Cementing mixed 47 sacks of Class A cement with a slurry weight of 15.6# per gallon and displaced with 11.7# per gallon of weighted fresh water gel 26 bbl displacement volume.
Plug at 7368'-6738'

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/31/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

3/24/2010 Operator changed from 2348, TRIAD RESOURCES INC to 8610, TRIAD HUNTER LLC

12/21/2011 Operator changed from 8610, TRIAD HUNTER LLC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296180000

Project: SWIW-15-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: FQ ENERGY SERVICES LLC Resp Co

Well Name: GREENWOOD UNIT (SWIW #15) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness cutting off of tubing and bond log of casing cement top on backside of casing was noted at 5040' with one tight spot noted@ 4286-4350' shot 4.5" off at 4235' set 250' cement plug.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/4/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

3/24/2010 Operator changed from 2348, TRIAD RESOURCES INC to 8610, TRIAD HUNTER LLC

12/21/2011 Operator changed from 8610, TRIAD HUNTER LLC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296180000

Project: SWIW-15-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: FQ ENERGY SERVICES LLC Resp Co

Well Name: GREENWOOD UNIT (SWIW #15) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Witness plugging operations.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/5/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

3/24/2010 Operator changed from 2348, TRIAD RESOURCES INC to 8610, TRIAD HUNTER LLC

12/21/2011 Operator changed from 8610, TRIAD HUNTER LLC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295770000

Project: SWIW-7-WASH

County: WASHINGTON Twp. LAWRENCE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: FQ ENERGY SERVICES LLC Resp Co

Well Name: HELEN F HALL (SWIW #7) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation and it was noted that two company owned vacuum trucks were unloading at the facility during our inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1830 Vac ANNULUSPRESSURE: 90 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/5/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

10/24/2014 Operator changed from 7434, VIRCO INC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation and it was noted that storage tank area was clean and unloading pad was clean and in good repair.

Note: One 25-542 vacuum truck was unloading at the facility at the time of my inspection and it was also noted that the 500 bbl. Storage tanks that were on site from there temporary operations have been removed from site.

Accompanied by _____

INJECTIONPRESSUR 1270 Vac ANNULUSPRESSURE: 800 Vac FLOWMETER: Vac

HAULERNO: 25542 LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/4/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that pump was not in operation during our inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1920 Vac ANNULUSPRESSURE: 40 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/5/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296850000

Project: SWIW-10-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: NEWELL RUN DISPOSAL WELL(S) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1890 Vac ANNULUSPRESSURE: 240 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/6/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296180000

Project: SWIW-15-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: FQ ENERGY SERVICES LLC Resp Co

Well Name: GREENWOOD UNIT (SWIW #15) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness setting of remaining cement plugs in well,cement stayed up good at surface.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/6/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

3/24/2010 Operator changed from 2348, TRIAD RESOURCES INC to 8610, TRIAD HUNTER LLC

12/21/2011 Operator changed from 8610, TRIAD HUNTER LLC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296580000

Project: SWIW-8-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: LONG RUN DISPOSAL WELL(SWI No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1675 Vac ANNULUSPRESSURE: 450 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/6/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167293950000

Project: SWIW-6-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: OHIO OIL GATHERING CORP II (S No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pumps were in operation and it was noted that plumbing to storage tanks has been replaced since my last inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1860 Vac ANNULUSPRESSURE: 320 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/6/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner APPALACHIAN OIL PURCHASERS INC

Former Owners

7/6/2001 Operator changed from 6357, APPALACHIAN OIL PURCHASERS INC to 2153, OOGC DISPOSAL CO #1

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Surface Facility Construction Contact: Phone
Address

Inspection Purpose: Status Check

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation during my inspection and several different brine haulers were unloading at the state route 7 facility today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1300 Vac ANNULUSPRESSURE: 380 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/17/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation during my inspection and several different brine haulers were unloading at the state route 7 facility today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1180 Vac ANNULUSPRESSURE: 840 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/17/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation during my inspection and several different brine haulers were unloading at the state route 7 facility today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1040 Vac ANNULUSPRESSURE: 460 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/17/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation and it was noted that one Huey Brothers vacuum truck was unloading at the facility during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1270 Vac ANNULUSPRESSURE: 540 Vac FLOWMETER: Vac

HAULERNO: 25456 LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/23/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was not in operation and it was noted that there was not a operator present during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 740 Vac ANNULUSPRESSURE: 145 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/23/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injectin pump was not in operation durin my inspection and according to company rep well is not being used much at this time it is taking any overflow from other wells that company owns in other counties within the state.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 25 Vac ANNULUSPRESSURE: 170 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/23/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167274010000

Project: SWIW-2-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was not in operation and it appears that wells are not being used much at this time.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 0 Vac ANNULUSPRESSURE: 200 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/2/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner BIG INJUN OIL & GAS INC.

Former Owners

12/30/1982 118 BIG INJUN OIL & GAS INC GeoDate 12/30/82

12/13/1984 642 LOTHES OIL & GAS INC GeoDate 12/13/84

5/3/1989 3133 PETROEL GeoDate 5/3/89

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167279580000

Project: SWIW-9-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN(SWIW#9) No.: 3 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was not in operation and it appears that wells are not being used much at this time.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 0 Vac ANNULUSPRESSURE: 210 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/2/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner CARPER WELL SERVICE

Former Owners

12/20/1984 3133 PETROEL GeoDate 12/20/84

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Note: Did not inspect state route 7 facility today.

Accompanied by _____

INJECTIONPRESSUR 1300 Vac ANNULUSPRESSURE: 400 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/2/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167293950000

Project: SWIW-6-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: OHIO OIL GATHERING CORP II (S No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness Producers Services perform 1500 gallon treatment on said well.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: 345 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/5/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner APPALACHIAN OIL PURCHASERS INC

Former Owners

7/6/2001 Operator changed from 6357, APPALACHIAN OIL PURCHASERS INC to 2153, OOGC DISPOSAL CO #1

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296850000

Project: SWIW-10-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: NEWELL RUN DISPOSAL WELL(S) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness Producers Services perform 1500 gallon treatment on said well.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: 265 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/5/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Note: Did not inspect state route 7 facility today.

Accompanied by _____

INJECTIONPRESSUR 1360 Vac ANNULUSPRESSURE: 600 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/2/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone
Address

Inspection Purpose: Status Check

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Note: Did not inspect state route 7 facility today.

Accompanied by _____

INJECTIONPRESSUR 1340 Vac ANNULUSPRESSURE: 840 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/2/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site today to witness 1000 acid treatment of said well, Producers Services pumped 1000 gallon of 15% acid at average treating pressure of 1005 psi and ISIP was noted at 766 psi.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 850 Vac ANNULUSPRESSURE: 500 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/30/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site today to witness Appalachia Solvents pressure treating truck perform MIT testing on said well they pressured up to 1280 psi and we monitored pressure for 15 minutes with no decline in pressure(TEST PASSED).

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: 1280 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/27/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed: 6/27/2017

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that well is not in operation at this time.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 25 Vac ANNULUSPRESSURE: 185 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/27/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation and it was noted that one Hall Drilling truck and one ECM and one Waste Management truck was unloading at the facility today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1270 Vac ANNULUSPRESSURE: 700 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/27/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 39.337440 WH_LONG: -81.674170

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness Producers Services perform 1500 gallon of 28% acid treatment on said well.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: 580 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/23/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that that well was not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1890 Vac ANNULUSPRESSURE: 55 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/31/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296180000

Project: SWIW-15-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: FQ ENERGY SERVICES LLC Resp Co

Well Name: GREENWOOD UNIT (SWIW #15) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that restoration work has not began and I called company rep Dave Casto and discussed there plan to restore site he stated they would possibly move equipment in on site 6/6/17 to restore site as required by ORC 1509.072.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/31/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

3/24/2010 Operator changed from 2348, TRIAD RESOURCES INC to 8610, TRIAD HUNTER LLC

12/21/2011 Operator changed from 8610, TRIAD HUNTER LLC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pumps were in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1420 Vac ANNULUSPRESSURE: 600 Vac FLOWMETER: 564377 Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/13/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167274010000

Project: SWIW-2-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Well not in operation at this time.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 35 Vac ANNULUSPRESSURE: 210 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/12/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner BIG INJUN OIL & GAS INC.

Former Owners

12/30/1982 118 BIG INJUN OIL & GAS INC GeoDate 12/30/82

12/13/1984 642 LOTHES OIL & GAS INC GeoDate 12/13/84

5/3/1989 3133 PETROEL GeoDate 5/3/89

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167279580000

Project: SWIW-9-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN(SWIW#9) No.: 3 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Well not in operation at this time.

Note: Walked flowline area to both wells on the lease today.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 50 Vac ANNULUSPRESSURE: 205 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/12/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner CARPER WELL SERVICE

Former Owners

12/20/1984 3133 PETROEL GeoDate 12/20/84

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pumps were in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1410 Vac ANNULUSPRESSURE: 550 Vac FLOWMETER: 1E+06 Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/13/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pumps were in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1405 Vac ANNULUSPRESSURE: 560 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/13/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296580000

Project: SWIW-8-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: LONG RUN DISPOSAL WELL(SWI No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump to this well was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1750 Vac ANNULUSPRESSURE: 625 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/24/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295770000

Project: SWIW-7-WASH

County: WASHINGTON Twp. LAWRENCE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: FQ ENERGY SERVICES LLC Resp Co

Well Name: HELEN F HALL (SWIW #7) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation during my inspection and it was noted that rain water has built up in dike area from all of the recent heavy rains told operator to pump water into storage tanks and properly dispose of it down hole.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1705 Vac ANNULUSPRESSURE: 80 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/24/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

10/24/2014 Operator changed from 7434, VIRCO INC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that well was not being used today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1950 Vac ANNULUSPRESSURE: 50 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/24/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296850000

Project: SWIW-10-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: NEWELL RUN DISPOSAL WELL(S) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump to this well was in operation during my inspection.

Note: Hard to get past creek crossing today due to recent heavy rains wasing out creek crossing.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1870 Vac ANNULUSPRESSURE: 260 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/24/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167293950000

Project: SWIW-6-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: OHIO OIL GATHERING CORP II (S No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump to this well was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1890 Vac ANNULUSPRESSURE: 400 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/24/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner APPALACHIAN OIL PURCHASERS INC

Former Owners

7/6/2001 Operator changed from 6357, APPALACHIAN OIL PURCHASERS INC to 2153, OOGC DISPOSAL CO #1

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness Producers Services perform 1500 gallon of 28% acid treatment on said well.

On site along with UIC staff member Jennifer Gringras to witness job.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/19/2017

Signature:

Date Compliance Issued:

DAVID BALL

Required action to be completed by:

Reviewed by:

Extended action completed:

Forward to:

Required action completed:

Duration: _____ hrs

Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness Producers Services perform 1500 gallon of 28% acid treatment on said well.

On site along with UIC staff member Jennifer Gringras to witness job.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/19/2017

Signature:

Date Compliance Issued:

DAVID BALL

Required action to be completed by:

Reviewed by:

Extended action completed:

Forward to:

Required action completed:

Duration: _____ hrs

Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness Producers Services perform 1500 gallon of 28% acid treatment on said well.

On site along with UIC staff member Jennifer Gringras to witness job.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/19/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pumps were in operation during my inspection and note flowline area from pump house to wellhead was walked today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1380 Vac ANNULUSPRESSURE: 760 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/15/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pumps were in operation during my inspection and note flowline area from pump house to wellhead was walked today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1430 Vac ANNULUSPRESSURE: 600 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/15/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pumps were in operation during my inspection and note flowline area from pump house to wellhead was walked today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1320 Vac ANNULUSPRESSURE: 540 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/15/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167279580000

Project: SWIW-9-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN(SWIW#9) No.: 3 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Well not in operation at this time.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 0 Vac ANNULUSPRESSURE: 200 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/24/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner CARPER WELL SERVICE

Former Owners

12/20/1984 3133 PETROEL GeoDate 12/20/84

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation during my inspection.

Note: One Energy Transport tanker unloading at the facility during my inspection.

Accompanied by _____

INJECTIONPRESSUR 1000 Vac ANNULUSPRESSURE: 120 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/24/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 840 Vac ANNULUSPRESSURE: 140 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/24/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167274010000

Project: SWIW-2-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Well not in operation at this time.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 0 Vac ANNULUSPRESSURE: 180 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/24/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner BIG INJUN OIL & GAS INC.

Former Owners

12/30/1982 118 BIG INJUN OIL & GAS INC GeoDate 12/30/82

12/13/1984 642 LOTHES OIL & GAS INC GeoDate 12/13/84

5/3/1989 3133 PETROEL GeoDate 5/3/89

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1275 Vac ANNULUSPRESSURE: 875 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/24/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167293950000

Project: SWIW-6-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: OHIO OIL GATHERING CORP II (S No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1850 Vac ANNULUSPRESSURE: 500 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/8/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner APPALACHIAN OIL PURCHASERS INC

Former Owners

7/6/2001 Operator changed from 6357, APPALACHIAN OIL PURCHASERS INC to 2153, OOGC DISPOSAL CO #1

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295770000

Project: SWIW-7-WASH

County: WASHINGTON Twp. LAWRENCE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: FQ ENERGY SERVICES LLC Resp Co

Well Name: HELEN F HALL (SWIW #7) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Surface Facility Construction Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump not in operation during my inspection.
Note: One company owned tanker and one 25-568 vacuum truck unloading at the facility today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1150 Vac ANNULUSPRESSURE: 200 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/8/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

10/24/2014 Operator changed from 7434, VIRCO INC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296580000

Project: SWIW-8-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: LONG RUN DISPOSAL WELL(SWI No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1780 Vac ANNULUSPRESSURE: 600 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/8/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296850000

Project: SWIW-10-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: NEWELL RUN DISPOSAL WELL(S) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1900 Vac ANNULUSPRESSURE: 400 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/8/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1860 Vac ANNULUSPRESSURE: 200 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/8/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296180000

Project: SWIW-15-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: FQ ENERGY SERVICES LLC Resp Co

Well Name: GREENWOOD UNIT (SWIW #15) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Final Restoration Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that final restoration work at site has been completed, pit was filled in and site has been graded and seeded and mulched and vegetation has began to grow and landowner is satisfied with all the work that has been performed at the site.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/18/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed: 9/18/2017

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

3/24/2010 Operator changed from 2348, TRIAD RESOURCES INC to 8610, TRIAD HUNTER LLC

12/21/2011 Operator changed from 8610, TRIAD HUNTER LLC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1270 Vac ANNULUSPRESSURE: 750 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/17/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation and it was noted that three Hall Drilling tankers were offloading at the facility during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1250 Vac ANNULUSPRESSURE: 600 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/27/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump to this well was not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1900 Vac ANNULUSPRESSURE: 180 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/24/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296180000

Project: SWIW-15-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: FQ ENERGY SERVICES LLC Resp Co

Well Name: GREENWOOD UNIT (SWIW #15) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Final Restoration Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Final restoration work at site is satisfactory, pits were filled in and site restored and vegetation has been established and we have received landowner waiver to leave existing lease road to top of hill and small area where parking area was will be used by landowner to store farm equipment.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/24/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed: 10/24/2017

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

3/24/2010 Operator changed from 2348, TRIAD RESOURCES INC to 8610, TRIAD HUNTER LLC

12/21/2011 Operator changed from 8610, TRIAD HUNTER LLC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection and it was noted that fresh water needs to be removed from dike area consulted with well operator and he stated they would pump it into storage tanks later today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 920 Vac ANNULUSPRESSURE: 20 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/27/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation during my inspection and it was noted that one Ohio Oil Gathering tanker and one Enervest vacuum truck was unloading at the facility during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1100 Vac ANNULUSPRESSURE: 100 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/27/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation and it was noted that three Hall Drilling tankers were on site offloading during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1400 Vac ANNULUSPRESSURE: 540 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/2/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation and it was noted that three Hall Drilling tankers were on site offloading during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1390 Vac ANNULUSPRESSURE: 750 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/2/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation and it was noted that three Hall Drilling tankers were on site offloading during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1420 Vac ANNULUSPRESSURE: 580 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/2/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296580000

Project: SWIW-8-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: LONG RUN DISPOSAL WELL(SWI No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump to this well was in operation on the day of my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1725 Vac ANNULUSPRESSURE: 595 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/15/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump to this well was in operation on the day of my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1890 Vac ANNULUSPRESSURE: 190 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/15/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296850000

Project: SWIW-10-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: NEWELL RUN DISPOSAL WELL(S) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump to this well was in operation on the day of my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1910 Vac ANNULUSPRESSURE: 420 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/15/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167293950000

Project: SWIW-6-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: OHIO OIL GATHERING CORP II (S No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation during y inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1870 Vac ANNULUSPRESSURE: 490 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/15/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner APPALACHIAN OIL PURCHASERS INC

Former Owners

7/6/2001 Operator changed from 6357, APPALACHIAN OIL PURCHASERS INC to 2153, OOGC DISPOSAL CO #1

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump to this well was in operation.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1410 Vac ANNULUSPRESSURE: 520 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/13/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was not in operation during my inspection and it was noted that two Energy Transport vacuum trucks were offloading at the facility during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 580 Vac ANNULUSPRESSURE: 500 Vac FLOWMETER: Vac

HAULERNO: 25601 LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/14/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site today to witness Producers Services perform 5000 gallon acid treatment on well.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: 590 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/13/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HEINRICH ENTERPRISES INC DBA WASHINGTON OPERA Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump to this well was in operation.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1390 Vac ANNULUSPRESSURE: 700 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/13/2017

Signature: _____

Date Compliance Issued: _____

DAVID BALL

Required action to be completed by: _____

Reviewed by: _____

Extended action completed: _____

Forward to: _____

Required action completed: _____

Duration: _____ hrs

Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC

12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC

12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.

12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC

12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection and it was noted that three Hall Drilling vacuum trucks were offloading during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1275 Vac ANNULUSPRESSURE: 500 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/14/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167279580000

Project: SWIW-9-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN(SWIW#9) No.: 3 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Well is not in operation at this time.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 0 Vac ANNULUSPRESSURE: 210 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/14/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner CARPER WELL SERVICE

Former Owners

12/20/1984 3133 PETROEL GeoDate 12/20/84

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167274010000

Project: SWIW-2-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Well is not in operation at this time.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 0 Vac ANNULUSPRESSURE: 175 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/14/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner BIG INJUN OIL & GAS INC.

Former Owners

12/30/1982 118 BIG INJUN OIL & GAS INC GeoDate 12/30/82

12/13/1984 642 LOTHES OIL & GAS INC GeoDate 12/13/84

5/3/1989 3133 PETROEL GeoDate 5/3/89

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection and it was noted that one Energy Transport vacuum truck was offloading at the facility during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1020 Vac ANNULUSPRESSURE: 20 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/14/2017

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296850000

Project: SWIW-10-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: NEWELL RUN DISPOSAL WELL(S) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump to this well was in operation today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1920 Vac ANNULUSPRESSURE: 400 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/9/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection and it was noted that six Hall Drilling vacuum trucks were offloading at the facility during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1350 Vac ANNULUSPRESSURE: 520 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/10/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that well appears not to be in service at this time.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1700 Vac ANNULUSPRESSURE: 210 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/9/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump to this well was in operation and it was noted that route 7 offload facility was extremely busy with brine hauling trucks.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1395 Vac ANNULUSPRESSURE: 710 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/10/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump to this well was in operation and it was noted that route 7 offload facility was extremely busy with brine hauling trucks.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1430 Vac ANNULUSPRESSURE: 600 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/10/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296580000

Project: SWIW-8-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: LONG RUN DISPOSAL WELL(SWI No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump to this well was in operation today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1860 Vac ANNULUSPRESSURE: 300 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/9/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295770000

Project: SWIW-7-WASH

County: WASHINGTON Twp. LAWRENCE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: FQ ENERGY SERVICES LLC Resp Co

Well Name: HELEN F HALL (SWIW #7) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was not in operation during my inspection and it was noted that one company owned vacuum truck was offloading during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1100 Vac ANNULUSPRESSURE: 200 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/9/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

10/24/2014 Operator changed from 7434, VIRCO INC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump to this well was in operation and it was noted that route 7 offload facility was extremely busy with brine hauling trucks.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1420 Vac ANNULUSPRESSURE: 500 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/10/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167293950000

Project: SWIW-6-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: OHIO OIL GATHERING CORP II (S No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump to this well was in operation today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1890 Vac ANNULUSPRESSURE: 250 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/9/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner APPALACHIAN OIL PURCHASERS INC

Former Owners

7/6/2001 Operator changed from 6357, APPALACHIAN OIL PURCHASERS INC to 2153, OOGC DISPOSAL CO #1

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167293950000

Project: SWIW-6-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: OHIO OIL GATHERING CORP II (S No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1875 Vac ANNULUSPRESSURE: 300 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/27/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner APPALACHIAN OIL PURCHASERS INC

Former Owners

7/6/2001 Operator changed from 6357, APPALACHIAN OIL PURCHASERS INC to 2153, OOGC DISPOSAL CO #1

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Well not being used much at this time.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1650 Vac ANNULUSPRESSURE: 230 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/27/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296850000

Project: SWIW-10-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: NEWELL RUN DISPOSAL WELL(S) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1910 Vac ANNULUSPRESSURE: 400 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/27/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296580000

Project: SWIW-8-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: LONG RUN DISPOSAL WELL(SWI No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1875 Vac ANNULUSPRESSURE: 300 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/27/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection and it was noted that one Viking and one Hall Drilling and one BSI vacuum truck was unloading at the site during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1390 Vac ANNULUSPRESSURE: 500 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/25/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167293950000

Project: SWIW-6-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: OHIO OIL GATHERING CORP II (S No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1790 Vac ANNULUSPRESSURE: 300 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/25/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner APPALACHIAN OIL PURCHASERS INC

Former Owners

7/6/2001 Operator changed from 6357, APPALACHIAN OIL PURCHASERS INC to 2153, OOGC DISPOSAL CO #1

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167274010000

Project: SWIW-2-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump not in operation today.

Called company rep and requested that fresh water within dike area be removed and properly disposed of.

Accompanied by _____

INJECTIONPRESSUR 200 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/18/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner BIG INJUN OIL & GAS INC.

Former Owners

12/30/1982 118 BIG INJUN OIL & GAS INC GeoDate 12/30/82

12/13/1984 642 LOTHES OIL & GAS INC GeoDate 12/13/84

5/3/1989 3133 PETROEL GeoDate 5/3/89

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167279580000

Project: SWIW-9-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN(SWIW#9) No.: 3 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Address

Inspection Purpose: Status Check

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump not in operation today.

Called company rep and requested that fresh water within dike area be removed and properly disposed of.

Accompanied by _____

INJECTIONPRESSUR 155 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/18/2018

Signature:

Date Compliance Issued:

DAVID BALL

Required action to be completed by:

Reviewed by:

Extended action completed:

Forward to:

Required action completed:

Duration: _____

hrs

Section/Name

Original Owner CARPER WELL SERVICE

Former Owners

12/20/1984 3133 PETROEL GeoDate 12/20/84

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection and it was noted that six Hall Drilling vacuum trucks were on site unloading during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1480 Vac ANNULUSPRESSURE: 500 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/18/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection, facility is currently in process of having storage tanks cleaned out by Waste Management.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1360 Vac ANNULUSPRESSURE: 340 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/21/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection, facility is currently in process of having storage tanks cleaned out by Waste Management.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1340 Vac ANNULUSPRESSURE: 360 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/21/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection, facility is currently in process of having storage tanks cleaned out by Waste Management.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1360 Vac ANNULUSPRESSURE: 540 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/21/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation today and it was noted that one Energy Transport tanker was on site during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1050 Vac ANNULUSPRESSURE: 25 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/21/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was not in operation during my inspection due to acid treatment jobs being performed on off setting wells in the area.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1200 Vac ANNULUSPRESSURE: 510 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/12/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness Producers Services perform 2800 gallon of 28% HCL acid treatment on said well.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/12/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness Producers Services perform 2800 gallon of 28% HCL acid treatment on said well.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/12/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Producers Services performed 2500 gallon acid treatment on said well today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/16/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone
Address

Inspection Purpose: Status Check

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation and it was noted that one Hall Drilling vacuum truck was offloading at the facility during our inspection.

Specific gravity of water from storage tank at the 676 site was noted @1.120 today.

Accompanied by _____

INJECTIONPRESSUR 1360 Vac ANNULUSPRESSURE: 550 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/18/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation and it was noted that one Hall Drilling vacuum truck was offloading at the facility during our inspection.

Specific gravity of water from storage tank at the 676 site was noted @1.120 today.

Accompanied by _____

INJECTIONPRESSUR 1340 Vac ANNULUSPRESSURE: 350 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/18/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation and it was noted that one Hall Drilling vacuum truck was offloading at the facility during our inspection.

Specific gravity of water from storage tank at the 676 site was noted @1.120 today.

Accompanied by _____

INJECTIONPRESSUR 1345 Vac ANNULUSPRESSURE: 360 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/18/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 39.403020 WH_LONG: -81.476750

Directions to site: state route 7 facility out behind pumphouse area.

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that Express Energy was moving conductor rig on site and should be setting and cementing the same tomorrow.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/12/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone
Address

Inspection Purpose: Status Check

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pumps were in operation today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1360 Vac ANNULUSPRESSURE: 370 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/13/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation and it was noted that two Oil Hauler trucks were on site along with one Hall Drilling and one Gas field Services vacuum truck.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1320 Vac ANNULUSPRESSURE: 375 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/3/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation during our inspection.

Note: On site to perform truck audits today.

Huey Brothers,Elite,Gasfield Services were on site during our time at the facility.

Accompanied by _____

INJECTIONPRESSUR 1310 Vac ANNULUSPRESSURE: 600 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/8/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Address

Inspection Purpose: Status Check

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pumps were in operation today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1370 Vac ANNULUSPRESSURE: 345 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/13/2018

Signature: _____

Date Compliance Issued:

DAVID BALL

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation and it was noted that two Oil Hauler trucks were on site along with one Hall Drilling and one Gas field Services vacuum truck.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1355 Vac ANNULUSPRESSURE: 345 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/3/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pumps were in operation today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1340 Vac ANNULUSPRESSURE: 550 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/13/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation and it was noted that two Oil Hauler trucks were on site along with one Hall Drilling and one Gas field Services vacuum truck.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1350 Vac ANNULUSPRESSURE: 550 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/3/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation during our inspection.

Note: On site to perform truck audits today.

Huey Brothers,Elite,Gasfield Services were on site during our time at the facility.

Accompanied by _____

INJECTIONPRESSUR 1300 Vac ANNULUSPRESSURE: 560 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/8/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation during my inspection and it was noted that owner was having stone hauled in and spread to help trucks from dragging out mud onto county road.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 980 Vac ANNULUSPRESSURE: 500 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/25/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295770000

Project: SWIW-7-WASH

County: WASHINGTON Twp. LAWRENCE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: FQ ENERGY SERVICES LLC Resp Co

Well Name: HELEN F HALL (SWIW #7) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection and it was noted that one company owned vacuum truck was offloading at the site during my inspection. Specific gravity on fluid today was noted at 1.060.

Accompanied by _____

INJECTIONPRESSUR 1640 Vac ANNULUSPRESSURE: 100 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/26/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

10/24/2014 Operator changed from 7434, VIRCO INC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation during my inspection.
Injection pump was in operation and it was noted that four Hall Drilling vacuum trucks were on site during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1450 Vac ANNULUSPRESSURE: 180 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/15/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation during my inspection and it was noted that there was no brine trucks on the pad during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1440 Vac ANNULUSPRESSURE: 180 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/3/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation during my inspection and it was noted that one Hall Drilling truck was offloading at the facility today.

Specific gravity today was noted at 1.100.

Accompanied by _____

INJECTIONPRESSUR 1480 Vac ANNULUSPRESSURE: 10 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/25/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that well does not appear to be used much at this time.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1850 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/27/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that well was not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1850 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/26/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296850000

Project: SWIW-10-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: NEWELL RUN DISPOSAL WELL(S) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that two out of the three injection pumps were in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1910 Vac ANNULUSPRESSURE: 460 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/27/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296580000

Project: SWIW-8-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: LONG RUN DISPOSAL WELL(SWI No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pumps were in operation during my inspection.

Note: 2" valve on tubing head will need to be replaced in the near future its getting hard to open and 1/4" valve needs to be replaced also.

Accompanied by _____

INJECTIONPRESSUR 1800 Vac ANNULUSPRESSURE: 560 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/27/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Drill / Deepen / Reopen Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that Mitchell Drilling was moving in on site.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/15/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167279580000

Project: SWIW-9-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN(SWIW#9) No.: 3 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 380 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/25/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner CARPER WELL SERVICE

Former Owners

12/20/1984 3133 PETROEL GeoDate 12/20/84

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167274010000

Project: SWIW-2-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 340 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/25/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner BIG INJUN OIL & GAS INC.

Former Owners

12/30/1982 118 BIG INJUN OIL & GAS INC GeoDate 12/30/82

12/13/1984 642 LOTHES OIL & GAS INC GeoDate 12/13/84

5/3/1989 3133 PETROEL GeoDate 5/3/89

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167293950000

Project: SWIW-6-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: OHIO OIL GATHERING CORP II (S No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that two out of the three injection pumps were in operation during my inspection.

Valves on annulus side of tubing is in need of replacement.

Accompanied by _____

INJECTIONPRESSUR 1870 Vac ANNULUSPRESSURE: 960 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/27/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner APPALACHIAN OIL PURCHASERS INC

Former Owners

7/6/2001 Operator changed from 6357, APPALACHIAN OIL PURCHASERS INC to 2153, OOGC DISPOSAL CO #1

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was not in operation during my inspection.
Note: Walked flowline path to monitor for any potential leakage.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 750 Vac ANNULUSPRESSURE: 10 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/3/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86
4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89
9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89
11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89
10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY
2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC
7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation during my inspection and it was noted that one company owned vacuum truck was offloading at the facility today.

Specific gravity today was noted at 1.040.

Accompanied by _____

INJECTIONPRESSUR 1010 Vac ANNULUSPRESSURE: 10 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/25/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295770000

Project: SWIW-7-WASH

County: WASHINGTON Twp. LAWRENCE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: FQ ENERGY SERVICES LLC Resp Co

Well Name: HELEN F HALL (SWIW #7) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: NOV Follow-up Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that well is currently shut in awaiting on plan to be submitted for repair/plug.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 980 Vac ANNULUSPRESSURE: 940 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/27/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

10/24/2014 Operator changed from 7434, VIRCO INC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation during our inspection.

Note: On site to perform truck audits today.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1310 Vac ANNULUSPRESSURE: 580 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/8/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation and it was noted that two BSI 25-468 tankers were on site offloading during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1450 Vac ANNULUSPRESSURE: 80 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/9/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site today to witness MIT pressure testing of annulus of tubing they applied 1250 psi and we monitored pressure for 15 minutes with no decline(TEST PASSED).

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 840 Vac ANNULUSPRESSURE: 1250 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/18/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed: 6/18/2018

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167279580000

Project: SWIW-9-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN(SWIW#9) No.: 3 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was not in operation and I was on site to witness MIT testing of said well, they applied 580 psi of pressure and we monitored it for thirty minutes with no decline in pressure.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 0 Vac ANNULUSPRESSURE: 580 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/10/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed: 7/10/2018

Duration: _____ hrs Section/Name

Original Owner CARPER WELL SERVICE

Former Owners

12/20/1984 3133 PETROEL GeoDate 12/20/84

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167274010000

Project: SWIW-2-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was not in operation and I was on site to witness MIT testing of said well, they applied 600 psi of pressure and we monitored it for thirty minutes with no decline in pressure.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 0 Vac ANNULUSPRESSURE: 600 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/10/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed: 7/10/2018

Duration: _____ hrs Section/Name

Original Owner BIG INJUN OIL & GAS INC.

Former Owners

12/30/1982 118 BIG INJUN OIL & GAS INC GeoDate 12/30/82

12/13/1984 642 LOTHES OIL & GAS INC GeoDate 12/13/84

5/3/1989 3133 PETROEL GeoDate 5/3/89

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation during my inspection.

Contacted company rep and discussed erosion issue on lease road going to wellhead he stated that he would contact a local contractor to make repairs as soon as possible.

Accompanied by _____

INJECTIONPRESSUR 960 Vac ANNULUSPRESSURE: 840 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/18/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167293950000

Project: SWIW-6-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: OHIO OIL GATHERING CORP II (S No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1870 Vac ANNULUSPRESSURE: 200 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/19/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner APPALACHIAN OIL PURCHASERS INC

Former Owners

7/6/2001 Operator changed from 6357, APPALACHIAN OIL PURCHASERS INC to 2153, OOGC DISPOSAL CO #1

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Note: Well operating at maximum allowable pressure.

Accompanied by _____

INJECTIONPRESSUR 1970 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/19/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296580000

Project: SWIW-8-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: LONG RUN DISPOSAL WELL(SWI No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1850 Vac ANNULUSPRESSURE: 30 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/19/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296850000

Project: SWIW-10-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: NEWELL RUN DISPOSAL WELL(S) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1910 Vac ANNULUSPRESSURE: 400 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/19/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295770000

Project: SWIW-7-WASH

County: WASHINGTON Twp. LAWRENCE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: FQ ENERGY SERVICES LLC Resp Co

Well Name: HELEN F HALL (SWIW #7) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Well is down for repair.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 810 Vac ANNULUSPRESSURE: 1020 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/19/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

10/24/2014 Operator changed from 7434, VIRCO INC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation and it was noted that three company owned vacuum trucks were offloading at the facility during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1080 Vac ANNULUSPRESSURE: 450 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/3/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Drill / Deepen / Reopen Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site today to witness bond logging of well it was determined that cement top on annulus of casing was verified at 1970' which is tied in to the preceding casing string.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/10/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Preliminary Restoration Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Still getting pad cleaned up preparing for service rig once convert permit is issued.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/21/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Casing String Witnessed Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness Baker Hughes log well ad then rig crew rigged up O'S power tons and casing crew to start running 7" casing into well.
Total Depth 6251'
Loggers total depth 6195'
7" casing ran to 6187' and C&J cemented it in place with 650 sacks of cement.
21 centralizers ran and 3 baskets and 1 shoe and 1 float insert

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/23/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Drill / Deepen / Reopen Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Drilling on fluid at 5400.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/12/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Drill / Deepen / Reopen Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Drilling at 4917' drilling on fluid.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/10/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Drill / Deepen / Reopen Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Drilling 8 3/4" hole on fluid at 4741'.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/9/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Drill / Deepen / Reopen Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Drilling Ohio shale section(dusting) 30 minute Kelly's.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/5/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Drill / Deepen / Reopen Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that Mitchell Drilling was at a depth of 936' and they took a deviation survey at 907' which was 1/4* out next survey will be at 1250' according to driller.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/28/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 39.402840 WH_LONG: -81.476910

Directions to site:

Inspection Type: Casing String Witnessed Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Mitchell Drilling ran 361' of 13.3/8" casing and hole depth was 400' of 17 1/2" hole and Cemenco cemented pipe in place with 315 sacks of Class A cement and they had 18 bbl of good cement returns and it stayed up good.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/24/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Drill / Deepen / Reopen Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that welders were still fabricating lines to closed loop system ,driller hopes to be drilling later today.

Note: Northwest side of location has a small slip area developing made well owner aware of it and we will monitor area for any future slippage.

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/22/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Drill / Deepen / Reopen Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that Mitchell Drilling was still rigging up equipment and they hope to be drilling by the end of the week.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/18/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Drill / Deepen / Reopen Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Reaming well bore trying to knock out ledge off of well bore so casing will run freely.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/25/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Casing String Witnessed Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness casing job, Decker Drilling drilled a 24" hole to 415' and attempted to run 369' of 18.625" casing pipe would not go they made two attempts to run casing but it failed and then decision was made to get reamers and attempt to run casing tomorrow.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/24/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Drill / Deepen / Reopen Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness cementing of conductor pipe.
Cement to surface and we left 12" in bottom of tin horn to ensure good seal to exposed soils.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/22/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site: State route 339 south of Veto south side of lease road at the existing facility.

Inspection Type: Casing String Witnessed Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness Ransom Drilling set conductor pipe, 32" hole to 100" and ran 100" of 26" casing and they will cement casing tomorrow.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/21/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Note: Eight different vacuum trucks were on site offloading during my inspection.

ECM-3

FQ-1

Hall Drilling-4

Accompanied by _____

INJECTIONPRESSUR 1460 Vac ANNULUSPRESSURE: 110 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/3/2018

Date Compliance Issued:

Required action to be completed by:

Extended action completed:

Required action completed:

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Signature: _____
DAVID BALL

Reviewed by: _____

Forward to: _____

Duration: _____ hrs Section/Name

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Casing String Witnessed Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Decker Rig 11 drilled to a depth of 4320' and ran 4296' of 9.625" casing and BJ Services cemented it in place with 765 sacks of Class A cement, two stage tool@3616'.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/3/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that well was not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1920 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/21/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296850000

Project: SWIW-10-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: NEWELL RUN DISPOSAL WELL(S) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

1.1 SG

Accompanied by _____

INJECTIONPRESSUR 1830 Vac ANNULUSPRESSURE: 410 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/21/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296580000

Project: SWIW-8-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: LONG RUN DISPOSAL WELL(SWI No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

1.1 SG

Accompanied by _____

INJECTIONPRESSUR 1620 Vac ANNULUSPRESSURE: 35 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/21/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation during my inspection and it was noted that three Hall Drilling transports were offloading during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1330 Vac ANNULUSPRESSURE: 190 Vac FLOWMETER: Vac

HAULERNO: 25361 LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/1/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation during my inspection and it was noted that three Hall Drilling transports were offloading during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1410 Vac ANNULUSPRESSURE: 205 Vac FLOWMETER: Vac

HAULERNO: 25361 LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/1/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation during my inspection and it was noted that three Hall Drilling transports were offloading during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1390 Vac ANNULUSPRESSURE: 410 Vac FLOWMETER: Vac

HAULERNO: 25361 LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/1/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167293950000

Project: SWIW-6-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: OHIO OIL GATHERING CORP II (S No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

1.1 SG

Accompanied by _____

INJECTIONPRESSUR 1820 Vac ANNULUSPRESSURE: 200 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/21/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner APPALACHIAN OIL PURCHASERS INC

Former Owners

7/6/2001 Operator changed from 6357, APPALACHIAN OIL PURCHASERS INC to 2153, OOGC DISPOSAL CO #1

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site today to witness Producers Services perform 2000 gallon acid treatment on said well.

Note: 28% HCL type acid used for treatment.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1250 Vac ANNULUSPRESSURE: 110 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/1/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pumps were in operation today and it was noted that facility was extremely busy today.
1.080 specific gravity.
Well operating at 1490 psi owner requested pressure increase and it was approved by Chief's Order 2017-498 allowing maximum pressure at 1490 psi.

Accompanied by _____

INJECTIONPRESSUR 1490 Vac ANNULUSPRESSURE: 100 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/21/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site today to witness pressure testing of 4" fiber spar flowline they applied 1100 psi and we monitored pressure for 15 minutes with no decline in pressure(TEST PASSED).
Note: Flowline is encased within a 12" outer casing.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/19/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Completion Testing Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness Producers Services perform acid treatment on Bass Island they pumped 2500 gallon of 28% HCL type acid, Applachian Wireline truck on site to perforate the Ohio Shale section and we will start packer in well tomorrow.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/12/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pumps were in operation today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1310 Vac ANNULUSPRESSURE: 560 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/21/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1360 Vac ANNULUSPRESSURE: 550 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/3/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pumps were in operation today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1320 Vac ANNULUSPRESSURE: 370 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/21/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1355 Vac ANNULUSPRESSURE: 370 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/3/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pumps were in operation today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1325 Vac ANNULUSPRESSURE: 350 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/21/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1370 Vac ANNULUSPRESSURE: 340 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/3/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation during my inspection.

Note: Walked flowline area to monitor area for any potential leaks none were found.

Accompanied by _____

INJECTIONPRESSUR 1000 Vac ANNULUSPRESSURE: 500 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/3/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation and it was noted that two Energy Transport tankers were on site offloading during my inspection.

Walked flowline area.

Accompanied by _____

INJECTIONPRESSUR 960 Vac ANNULUSPRESSURE: 715 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/23/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 850 Vac ANNULUSPRESSURE: 445 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/6/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167274010000

Project: SWIW-2-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was not in operation during my inspection.

Note: Well does not appear to be used much at this time.

Accompanied by _____

INJECTIONPRESSUR 110 Vac ANNULUSPRESSURE: 400 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/6/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner BIG INJUN OIL & GAS INC.

Former Owners

12/30/1982 118 BIG INJUN OIL & GAS INC GeoDate 12/30/82

12/13/1984 642 LOTHES OIL & GAS INC GeoDate 12/13/84

5/3/1989 3133 PETROEL GeoDate 5/3/89

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167279580000

Project: SWIW-9-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co

Well Name: DAVIS-HUFFMAN(SWIW#9) No.: 3 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Address

Inspection Purpose: Status Check

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was not in operation during my inspection.

Note: Well does not appear to be used much at this time.

Accompanied by _____

INJECTIONPRESSUR 135 Vac ANNULUSPRESSURE: 400 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/6/2018

Signature:

Date Compliance Issued:

DAVID BALL

Required action to be completed by:

Reviewed by:

Extended action completed:

Forward to:

Required action completed:

Duration: _____ hrs

Section/Name

Original Owner CARPER WELL SERVICE

Former Owners

12/20/1984 3133 PETROEL GeoDate 12/20/84

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation.

Note: Walked flowline area to check for any potential leaks none were found.

Accompanied by _____

INJECTIONPRESSUR 1000 Vac ANNULUSPRESSURE: 170 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/6/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1300 Vac ANNULUSPRESSURE: 110 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/6/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 400 Vac ANNULUSPRESSURE: 190 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/6/2018

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Completion Testing Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Knox Energy service rig on site running in hole to set mechanical bridge plug in preparation for upcoming acid treatment of Ohio Shale section of wellbore.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/11/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site today to witness pressure testing of new fiber spar flowline and new manifold plumbing from pumphouse Full Circle pressure recorded testing @ 11150 psi and we monitored it for one hour with no pressure loss, took photo of chart and forwarded it to supervisor.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/14/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed: 3/14/2019

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness pressure testing of flowline, today we did not perform test due to fact that flanges on line were not rated for maximum pressure required they will have to change out flanges to a higher pressure rating and they plan on testing line next week.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 0 Vac ANNULUSPRESSURE: 585 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/7/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that contractor was working on flowline to wellhead and they plan on pressure testing it later this week according to company rep.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 0 Vac ANNULUSPRESSURE: 580 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/4/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that equipment has been moved in in preparation to start constructing flowline to wellhead.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/13/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site today to witness tubing/packer/centralizers run in well and packer set and witness testing of said well.

Packer at 4184'
tested@1070 psi

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/22/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed: 1/22/2019

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Completion Testing Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Service rig retrieving bridge plug today hope to start packer and tubing in well on 1/22/19.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/18/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Completion Testing Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Producers Services on site to perform water frack on said well in the shale portion of wellbore, prior to frac they spotted 2000 gallon of 28% HCL type acid and then they began water frac reaching 41 bpm and they treated well with 3500 bbl. of water .

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/17/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Completion Testing Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Producers Services rigging up frack iron preparing for job tomorrow, Canary wellhead group on site to replace frack valve on stack.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/16/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pumps were in operation during my inspection.

Three Hall Drilling tankers were on site offloading during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1390 Vac ANNULUSPRESSURE: 425 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/16/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pumps were in operation during my inspection.

Three Hall Drilling tankers were on site offloading during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1420 Vac ANNULUSPRESSURE: 310 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/16/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pumps were in operation during my inspection.

Three Hall Drilling tankers were on site offloading during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1410 Vac ANNULUSPRESSURE: 70 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/16/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295770000

Project: SWIW-7-WASH

County: WASHINGTON Twp. LAWRENCE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: FQ ENERGY SERVICES LLC Resp Co

Well Name: HELEN F HALL (SWIW #7) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that well is still down waiting on repair or possible plugging of the well.

Note: Fresh water has built up in tank area, called company rep and requested that they remove water to allow for volume in the event of spill.

Accompanied by _____

INJECTIONPRESSUR 700 Vac ANNULUSPRESSURE: 650 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/14/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

10/24/2014 Operator changed from 7434, VIRCO INC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that well was not in operation due to electrical contractor making upgrades to service at the site.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/28/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump to this well was in operation during my inspection.

Note: Annulus pressure on tubing has dropped to zero will contact company and request pressure be applied to it.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1860 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/28/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296580000

Project: SWIW-8-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: LONG RUN DISPOSAL WELL(SWI No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump to this well was not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1650 Vac ANNULUSPRESSURE: 100 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/28/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296850000

Project: SWIW-10-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: NEWELL RUN DISPOSAL WELL(S) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump to this well was in operation during my inspection.

Note: Lease road to wellhead needs to be addressed it is partially washed out at creek crossing.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1860 Vac ANNULUSPRESSURE: 320 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/28/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that well was not in operation due to electrical contractor making upgrades to service at the site.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/28/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pumps were in operation during my inspection and it was noted that three BSI vacuum trucks were on site during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 380 Vac ANNULUSPRESSURE: 190 Vac FLOWMETER: Vac

HAULERNO: 25391 LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/4/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pumps were in operation during my inspection and it was noted that three BSI vacuum trucks were on site during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1250 Vac ANNULUSPRESSURE: 100 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/4/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation during my inspection.

Noted two Hall Drilling vacuum trucks were offloading during my inspection at the state route 7 facility.

Accompanied by _____

INJECTIONPRESSUR 1390 Vac ANNULUSPRESSURE: 70 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/4/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation during my inspection.

Noted two Hall Drilling vacuum trucks were offloading during my inspection at the state route 7 facility.

Accompanied by _____

INJECTIONPRESSUR 1410 Vac ANNULUSPRESSURE: 290 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/4/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1380 Vac ANNULUSPRESSURE: 420 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/4/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167293950000

Project: SWIW-6-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: OHIO OIL GATHERING CORP II (S No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump to this well was in operation during my inspection.

Note: Annulus pressure on tubing has dropped to zero will contact company and request pressure be applied to it.

Only one pump running in pumphouse during my inspection.

Accompanied by _____

INJECTIONPRESSUR 1860 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/28/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner APPALACHIAN OIL PURCHASERS INC

Former Owners

7/6/2001 Operator changed from 6357, APPALACHIAN OIL PURCHASERS INC to 2153, OOGC DISPOSAL CO #1

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation during my inspection and it was noted that two Energy Contractors tankers were on site offloading during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 860 Vac ANNULUSPRESSURE: 500 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/21/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation during my inspection and it was noted that two Energy Transport tankers were on site offloading during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1060 Vac ANNULUSPRESSURE: 180 Vac FLOWMETER: Vac

HAULERNO: 25601 LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/21/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pumps were in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1420 Vac ANNULUSPRESSURE: 320 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/15/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pumps were in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1400 Vac ANNULUSPRESSURE: 70 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/15/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pumps were in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1390 Vac ANNULUSPRESSURE: 430 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/15/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to meet with contractors to discuss upcoming plug back operation.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1860 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/25/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Preliminary Restoration Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Restoration work at the site is satisfactory there was no pits used too drill the well and site has been restored by landowner.

Note: Electrical service to facility has contractors working on upgrades to service and once work is completed they plan on installing new injection pumps.

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/21/2019

Date Compliance Issued:

Required action to be completed by:

Extended action completed:

Required action completed: 3/21/2019

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Signature: _____

DAVID BALL

Reviewed by: _____

Forward to: _____

Duration: _____ hrs Section/Name

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness Producers Services perform 1500 gallon acid treatment on said well, average pressure during pumping was noted at 1184 psi and they pumped at a rate of 3bpm and ISIP was noted at 847 psi.

28% HCL ACID WAS USED.

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/5/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Preliminary Restoration Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Restoration work at the site is satisfactory there was no pits used too drill the well and site has been restored by landowner.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/21/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed: 3/21/2019

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site today to witness Producers Services perform 2000 gallon acid treatment on well, average pressure during job was 451 psi and maximum pressure was noted at 491 psi and ISIP was noted at 412 psi rigged down equipment and moved over to do the number two well.

28% HCL acid was used.

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/5/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site today to witness pressure testing of dual flowline going to wellhead,they applied 1175 psi and we monitored pressure for 45 minutes with no pressure loss(test passed).

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 250 Vac ANNULUSPRESSURE: 300 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/5/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed: 5/5/2019

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site today to witness start up of injection operations of well ,owner recently received approval for injections operations to begin

Note: well had 670 psi of pressure prior to start up and pressure reached 900 psi then began pressure decrease and during pumping operations it fell to 700 and was still falling during testing period.

Accompanied by _____

INJECTIONPRESSUR 670 Vac ANNULUSPRESSURE: 200 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/23/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation during my inspection.

Noted three Hall Drilling vacuum trucks on site during my inspection.

Accompanied by _____

INJECTIONPRESSUR 1450 Vac ANNULUSPRESSURE: 500 Vac FLOWMETER: Vac

HAULERNO: 25361 LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/5/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pumps were in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1230 Vac ANNULUSPRESSURE: 720 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/23/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pumps were in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1260 Vac ANNULUSPRESSURE: 365 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/23/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pumps were in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1230 Vac ANNULUSPRESSURE: 715 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/23/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspected site along with Dan Goins and inspection revealed that injection pump was not in operation today and we took water sample from well and took it to divisions lab for testing.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 400 Vac ANNULUSPRESSURE: 50 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/18/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1300 Vac ANNULUSPRESSURE: 370 Vac FLOWMETER: 624006 Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/2/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was not in operation during my inspection.

Note: Four Hall Drilling trucks and two Gasfield Services vacuum trucks were on site offloading during my inspection.

Accompanied by _____

INJECTIONPRESSUR 100 Vac ANNULUSPRESSURE: 1000 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/2/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that one injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 690 Vac ANNULUSPRESSURE: 200 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/15/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was being replaced and water was being pumped up the hill to the other pumphouse and being disposed of in the other three wells that they own.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 500 Vac ANNULUSPRESSURE: 200 Vac FLOWMETER: 406589 Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/2/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was not in operation during my inspection.
Three Hall Drilling vacuum trucks on site during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 300 Vac ANNULUSPRESSURE: 1140 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/2/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Note: Four Hall Drilling trucks and two Gasfield Services vacuum trucks were on site offloading during my inspection.

Accompanied by _____

INJECTIONPRESSUR 650 Vac ANNULUSPRESSURE: 1200 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/2/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296580000

Project: SWIW-8-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: LONG RUN DISPOSAL WELL(SWI No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that well is in operation.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1800 Vac ANNULUSPRESSURE: 525 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/26/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167293950000

Project: SWIW-6-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: OHIO OIL GATHERING CORP II (S No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that well is in operation.

ID at wellhead has been updated since my last inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1830 Vac ANNULUSPRESSURE: 100 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/26/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner APPALACHIAN OIL PURCHASERS INC

Former Owners

7/6/2001 Operator changed from 6357, APPALACHIAN OIL PURCHASERS INC to 2153, OOGC DISPOSAL CO #1

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167293950000

Project: SWIW-6-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: OHIO OIL GATHERING CORP II (S No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pumps were in operation during my inspection.

Note: I.D. needs to be refreshed it starting to fade out.

Accompanied by _____

INJECTIONPRESSUR 1830 Vac ANNULUSPRESSURE: 100 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/22/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner APPALACHIAN OIL PURCHASERS INC

Former Owners

7/6/2001 Operator changed from 6357, APPALACHIAN OIL PURCHASERS INC to 2153, OOGC DISPOSAL CO #1

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1140 Vac ANNULUSPRESSURE: 80 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/2/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296850000

Project: SWIW-10-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: NEWELL RUN DISPOSAL WELL(S) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pumps were in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1820 Vac ANNULUSPRESSURE: 300 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/22/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295770000

Project: SWIW-7-WASH

County: WASHINGTON Twp. LAWRENCE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: FQ ENERGY SERVICES LLC Resp Co

Well Name: HELEN F HALL (SWIW #7) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Well is currently not in operation waiting on owner to repair/replace tubing and packer in well.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 690 Vac ANNULUSPRESSURE: 700 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/22/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

10/24/2014 Operator changed from 7434, VIRCO INC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation and it was noted that two Energy Transport tankers were on site offloading during my inspection.

Walked flowline area.

Accompanied by

INJECTIONPRESSUR 1415 Vac ANNULUSPRESSURE: 285 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/23/2019

Signature: DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by:

Extended action completed:

Forward to:

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC

12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC

12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.

12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC

12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that one injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1270 Vac ANNULUSPRESSURE: 385 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/15/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296580000

Project: SWIW-8-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: LONG RUN DISPOSAL WELL(SWI No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pumps were in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1810 Vac ANNULUSPRESSURE: 520 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/22/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that one injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1315 Vac ANNULUSPRESSURE: 190 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/15/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that one injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1285 Vac ANNULUSPRESSURE: 490 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/15/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump to this well was in operation during my inspection.

Barrel counter not working properly Silversmith has been notified according to company rep.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1250 Vac ANNULUSPRESSURE: 710 Vac FLOWMETER: 190385 Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/2/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump was in operation during my inspection and it was noted that one Energy Transport vacuum truck was on site offloading during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1190 Vac ANNULUSPRESSURE: 250 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/2/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation during my inspection.

Note: Walked flowline to monitor for any potential leaks none were found.

Accompanied by _____

INJECTIONPRESSUR 1100 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/2/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pumps were in operation during my inspection.

Note: walked flowline area to monitor area for any signs of leaks.

Accompanied by _____

INJECTIONPRESSUR 1390 Vac ANNULUSPRESSURE: 590 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/23/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295770000

Project: SWIW-7-WASH

County: WASHINGTON Twp. LAWRENCE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: FQ ENERGY SERVICES LLC Resp Co Same as Operator

Well Name: HELEN F HALL (SWIW #7) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Well down for repair/possible plugging operation.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 860 Vac ANNULUSPRESSURE: 890 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/5/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

10/24/2014 Operator changed from 7434, VIRCO INC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was not in operation during my inspection.
Three Hall Drilling vacuum trucks on site during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 700 Vac ANNULUSPRESSURE: 1100 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/2/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation and it was noted that two Energy Transport tankers were on site offloading during my inspection.

Walked flowline area.

Accompanied by _____

INJECTIONPRESSUR 1390 Vac ANNULUSPRESSURE: 465 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/23/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump to this well not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 980 Vac ANNULUSPRESSURE: 720 Vac FLOWMETER: 999529 Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/2/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that well appears to be in operation, owner is planning on plug back operations too begin in the near future.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1860 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/26/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by: _____

Extended action completed: _____

Required action completed: _____

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pumps were in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1820 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/22/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296850000

Project: SWIW-10-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: NEWELL RUN DISPOSAL WELL(S) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that well is in operation.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1830 Vac ANNULUSPRESSURE: 300 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/26/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Stopped by site for update rig crew not on site during the time I was on site.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/10/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167274010000

Project: SWIW-2-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co Same as Operator

Well Name: DAVIS-HUFFMAN No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

One company owned vacuum truck was backing in to unload as I was preparing to leave site.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 340 Vac ANNULUSPRESSURE: 200 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/26/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner BIG INJUN OIL & GAS INC.

Former Owners

12/30/1982 118 BIG INJUN OIL & GAS INC GeoDate 12/30/82

12/13/1984 642 LOTHES OIL & GAS INC GeoDate 12/13/84

5/3/1989 3133 PETROEL GeoDate 5/3/89

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167279580000

Project: SWIW-9-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co Same as Operator

Well Name: DAVIS-HUFFMAN(SWIW#9) No.: 3 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump was in operation during my inspection.

Noted new fence constructed around containment area.

Accompanied by _____

INJECTIONPRESSUR 380 Vac ANNULUSPRESSURE: 200 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/17/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner CARPER WELL SERVICE

Former Owners

12/20/1984 3133 PETROEL GeoDate 12/20/84

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation and it was noted that five Hall Drilling vacuum trucks were on site offloading during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 600 Vac ANNULUSPRESSURE: 810 Vac FLOWMETER: Vac

HAULERNO: 25361 LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/17/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167279580000

Project: SWIW-9-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co Same as Operator

Well Name: DAVIS-HUFFMAN(SWIW#9) No.: 3 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that this well is currently not being used.

It appeared that landowner knocked off pressure gauge on annulus side of wellhead when he was brush hogging the field.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 10 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/26/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner CARPER WELL SERVICE

Former Owners

12/20/1984 3133 PETROEL GeoDate 12/20/84

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co Same as Operator

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation during my inspection.

Noted 160 psi on 8.625" casing head today.

Accompanied by _____

INJECTIONPRESSUR 970 Vac ANNULUSPRESSURE: 110 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/17/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167293950000

Project: SWIW-6-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: OHIO OIL GATHERING CORP II (S No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pumps were not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1700 Vac ANNULUSPRESSURE: 200 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/30/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner APPALACHIAN OIL PURCHASERS INC

Former Owners

7/6/2001 Operator changed from 6357, APPALACHIAN OIL PURCHASERS INC to 2153, OOGC DISPOSAL CO #1

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site today to witness wireline truck run gauge ring in hole to determine where to set retainer they ran a 3.75" tool to 7226' and then came out of hole to run a 10K retainer in hole and once set they will start 2.3/8" tubing in hole tomorrow.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/8/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296580000

Project: SWIW-8-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: LONG RUN DISPOSAL WELL(SWI No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pumps were not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1710 Vac ANNULUSPRESSURE: 540 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/30/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicate that a service rig was on site but not rigged up at this time, well is to be plugged back in the near future.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1850 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/30/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site today to attempt to set bottom hole plug, stung into retainer and tried to pump water unable to do so after several **attempts decision was made to pull out of retainer and once they did retainer wouldn't shut had to kill well with 15.6# drilling fluid and shut well in until a safe plan was put together to get bottom hole plug set.**

Note: Told operator that cement retainer would have to be drilled out and hole cleaned out to the Medina formation.

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/12/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site today to witness Unlimited Energy Services rig run tubing in hole to possibly set bottom hole plug they didn't get to bottom today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/9/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296850000

Project: SWIW-10-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: NEWELL RUN DISPOSAL WELL(S) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pumps were not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1740 Vac ANNULUSPRESSURE: 310 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/30/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167274010000

Project: SWIW-2-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co Same as Operator

Well Name: DAVIS-HUFFMAN No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump was in operation during my inspection.

Noted new fence constructed around containment area.

Accompanied by _____

INJECTIONPRESSUR 240 Vac ANNULUSPRESSURE: 305 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/17/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner BIG INJUN OIL & GAS INC.

Former Owners

12/30/1982 118 BIG INJUN OIL & GAS INC GeoDate 12/30/82

12/13/1984 642 LOTHES OIL & GAS INC GeoDate 12/13/84

5/3/1989 3133 PETROEL GeoDate 5/3/89

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump not in operation during my inspection

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1000 Vac ANNULUSPRESSURE: 200 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 9/17/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co Same as Operator

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Address

Inspection Purpose: Status Check

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation during my inspection.

Note: Took water sample of injection fluids taking them to lab to be tested for analytical results.

Accompanied by _____

INJECTIONPRESSUR 1080 Vac ANNULUSPRESSURE: 10 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/24/2020

Signature:

Date Compliance Issued:

DAVID BALL

Required action to be completed by:

Reviewed by:

Extended action completed:

Forward to:

Required action completed:

Duration: _____ hrs

Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296580000

Project: SWIW-8-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: LONG RUN DISPOSAL WELL(SWI No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pumps were not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1520 Vac ANNULUSPRESSURE: 10 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/30/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to bond log 7" casing string cement top was noted @2530' they ran a total of 4503' of 7" casing with stage packer @4240' and slotted casing below and Lightning Services cemented casing in place with 210 sacks of Class A cement with a yield of 1.29 and cement weight was 15#. Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/27/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation during my inspection.

On site to witness pressure testing of 3" HDP plastic line that will be used to transfer backwash water from filter house to temp facility they tested line@82 psi and we monitored pressure for 15 minutes with no decline in pressure.

Accompanied by _____

INJECTIONPRESSUR 940 Vac ANNULUSPRESSURE: 5 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/7/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pumps were not in operation during my inspection.

DXP Services changing out pump barrel on pump number two at the 676 pumphouse.

Accompanied by _____

INJECTIONPRESSUR 990 Vac ANNULUSPRESSURE: 400 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/26/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Owner still trying to get well to equalize so they can pull packer and injection string.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/22/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump to this well was not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1120 Vac ANNULUSPRESSURE: 20 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/23/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Well currently not hooked up, plug back interval was unsuccessful.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/30/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co Same as Operator

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pup was in operation during my inspection and had conversation with operator concerning getting wellhead on 4.5" casing and 8.625" surface casing.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1100 Vac ANNULUSPRESSURE: 10 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/27/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness releasing of packer and killing of well, Baker Tool hand on site to release packer and they killed well with 10.5ppg of brine 94 bbl. Let well equalize and attempted to pull packer.

Packer not pulled from well today.

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/21/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Reviewed by: _____

Required action to be completed by:

Forward to: _____

Extended action completed:

Duration: _____ hrs Section/Name

Required action completed:

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Cleaning out bottom of open hole section with 8.750" tri-cone bit.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/7/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297680000

Project:

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: REDBIRD (SWIW #25) No.: 5 WH_LAT 39.335180 WH_LONG: 81.678180

Directions to site:

Inspection Type: Drill / Deepen / Reopen Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site today to witness 100' of 20" conductor pipe run and cemented in place and cellar was set and bottom sealed with 12" cement in bottom of cellar.
Lightning Services drilled and cemented hole.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/12/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297680000

Project:

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: REDBIRD (SWIW #25) No.: 5 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Still on site to witness MIT testing of well they applied 1200 psi to annulus of tubing and monitored pressure for 15 minutes with no decline.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: 1200 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/1/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296850000

Project: SWIW-10-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: NEWELL RUN DISPOSAL WELL(S) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pumps were not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1510 Vac ANNULUSPRESSURE: 410 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/30/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167293950000

Project: SWIW-6-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: OHIO OIL GATHERING CORP II (S No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1620 Vac ANNULUSPRESSURE: 1560 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/20/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner APPALACHIAN OIL PURCHASERS INC

Former Owners

7/6/2001 Operator changed from 6357, APPALACHIAN OIL PURCHASERS INC to 2153, OOGC DISPOSAL CO #1

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297680000

Project:

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: REDBIRD (SWIW #25) No.: 5 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Casing String Witnessed Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Decker Drilling rig#8 drilled a 17 1/2" hole to a depth of 364' and ran 336' of 13 3/8" casing equipped with guide shoe and three centralizers and one cement basket and Lightning Services cemented it in place with 309 sacks of Class A cement and they had approximately 15 bbl. of good cement returns.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/18/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump to this well was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 950 Vac ANNULUSPRESSURE: 310 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/23/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pumps were not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 600 Vac ANNULUSPRESSURE: 280 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/26/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site today to witness running of injection string and packer into well, ran a total of 4503' of 4.5" tubing and packer depth is at 4235' center of elements and there is 233' of tail pipe below packer.

Circulated 84 bbl. of fresh water and inhibitor with 5 gal of inhibitor and pressure tested at 1100 psi with no decline in pressure.

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: 1100 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/28/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed: 5/28/2020

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297680000

Project:

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: REDBIRD (SWIW #25) No.: 5 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Casing String Witnessed Contact: Phone
Address

Inspection Purpose: Status Check

Type of Notification Contact DAVID BALL

Inspection Comments:

Decker Rig#8 drilled to a total depth of 4660' and Applachian Wireline ran required logs on well and there total depth was noted@4659' ,they ran a total of 4627' of 7" casing and cement packer was set@4372' and BJ Services cemented casing in place with 762 sacks of cement.

6 joints of slotted casing below cement packer,10 centralizers were used and 2 cement baskets and 1-stage tool and packer.

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/26/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co Same as Operator

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Note still 180 psi on annulus of production casing.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1100 Vac ANNULUSPRESSURE: 730 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/1/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co Same as Operator

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation during my inspection and it was noted that three company owned tankers were offloading during my inspection.

Noted 180 psi on annulus between 4.5" production casing and 8.625" surface casing.

Accompanied by _____

INJECTION PRESSURE: 1110 Vac ANNULUS PRESSURE: 750 Vac FLOWMETER: Vac

HAULER NO: LISCENSE_NUM:

LANDOWNER WAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/22/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167293950000

Project: SWIW-6-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: OHIO OIL GATHERING CORP II (S No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pumps were not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1500 Vac ANNULUSPRESSURE: 700 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/30/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner APPALACHIAN OIL PURCHASERS INC

Former Owners

7/6/2001 Operator changed from 6357, APPALACHIAN OIL PURCHASERS INC to 2153, OOGC DISPOSAL CO #1

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump to this well was not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 850 Vac ANNULUSPRESSURE: 1370 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/23/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co Same as Operator

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was not in operation today wellsite is shut down till Monday.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 700 Vac ANNULUSPRESSURE: 140 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/29/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Well is currently down for injection pump repair.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 180 Vac ANNULUSPRESSURE: 960 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/23/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site today to witness approved cementing plan of annular space between 9.625" casing and 13.375" casing strings Lighting Cement Company pumped 400 sacks of 14.6 ppg and then mixed 400 sacks of 15.6 ppg and 1/2# of flake per sack and pumped in down annular space once cement was pumped valves on wellhead were shut and company will check and open valve on Wednesday to check and see if any pressure is present.

800 sacks of Class A cement was used for this portion of approved plan.
Plan on releasing packer next week and then perform more cement work on said well.

Accompanied by _____

INJECTIONPRESSUR 170 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/13/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co Same as Operator

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation during my inspection.

Noted that annulus between 8.625" and production casing has 180 psi on it.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1110 Vac ANNULUSPRESSURE: 1000 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/29/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&G

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump to this well was not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1100 Vac ANNULUSPRESSURE: 300 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/7/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site today to witness Lighting Services pump 800 sack squeeze job cement was mixed at a weight of 14.6PPG with 2%gel and 1/4# flake per sack in the first 400 sacks then the remaining 400 sacks was mixed with just 1/4#flake,cement was locked in place with 900 psi.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/11/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Currently drilling cement out of inside of 9.625" currently at 3700' should be done drilling cement this evening.

Request from division to collect water sample from storage tanks and deliver them to lab.

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/14/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297680000

Project:

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: REDBIRD (SWIW #25) No.: 5 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site today to witness bond logging of production casing,Appalachian Well Surveys logged well and cement top was determined to be at 1510' which is 509' inside of previous casing string.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/29/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297680000

Project:

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: REDBIRD (SWIW #25) No.: 5 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness running of tubing and packer in said well, center of element on packer is at 4311.67.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/30/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

O site today to witness running of 7" casing and cementing it in place they ran a total of 4503' of casing and cementing packer was set at 4269' and they ran 5 centralizers and 1-cement basket and Lightning Services cemented casing in place with 208 sacks of Class A CEMENT 15# PER SACK AND A YIELD OF 1.29.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/22/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pumps were not in operation during my inspection.

DXP Services changing out pump barrel on pump number two at the 676 pumphouse.

Accompanied by _____

INJECTIONPRESSUR 1040 Vac ANNULUSPRESSURE: 435 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/26/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296580000

Project: SWIW-8-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: LONG RUN DISPOSAL WELL(SWI No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pumps were not in operation during my inspection.

Company rep stated they plan on starting pumps later this week.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1560 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/20/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296850000

Project: SWIW-10-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: NEWELL RUN DISPOSAL WELL(S) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1600 Vac ANNULUSPRESSURE: 400 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/20/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Well currently setting idle recent plug back to upper formations to inject into was unsuccessful.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/20/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump to this well was not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 850 Vac ANNULUSPRESSURE: 310 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/23/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump to this well was not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 930 Vac ANNULUSPRESSURE: 365 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/7/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to pressure test flowline to injection well we tested line at 1240 psi with no decline in pressure in a one hour test period.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/12/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed: 6/12/2020

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Currently still trying to get well equalized, mixing salt to weight up water to proper kill weight.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 4/24/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation during my inspection.

Noted three Waters Edge Oilfield Services vacuum trucks on site offloading during my inspection.

Accompanied by _____

INJECTIONPRESSUR 1470 Vac ANNULUSPRESSURE: 600 Vac FLOWMETER: Vac

HAULERNO: 25544 LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 3/23/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pumps were not in operation during my inspection.

DXP Services changing out pump barrel on pump number two at the 676 pumphouse.

Accompanied by _____

INJECTIONPRESSUR 800 Vac ANNULUSPRESSURE: 225 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/26/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone
Address

Inspection Purpose: Status Check

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump to this well was not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 780 Vac ANNULUSPRESSURE: 235 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 5/7/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297710000

Project:

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: ARROWHEAD ROAD SERVICES LLC Resp Co Same as Operator

Well Name: ARROWHEAD ROAD SERVICES LL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Drill / Deepen / Reopen Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact BRANDON MITCHELL

Inspection Comments:

I conducted a status check on the well location for the Arrowhead Services LLC #1 disposal well today. No personnel or equipment was on location at the time of my inspection. I did not observe any issues during the inspection. Time of inspection: 1:40 PM. Weather: 70 degrees F, Sunny
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/8/2020

Signature: _____
BRANDON MITCHELL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner ARROWHEAD ROAD SERVICES LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297710000

Project:

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: ARROWHEAD ROAD SERVICES LLC Resp Co Same as Operator

Well Name: ARROWHEAD ROAD SERVICES LL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Drill / Deepen / Reopen Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact BRANDON MITCHELL

Inspection Comments:

I conducted a status check on the well location for the Arrowhead Services LLC #1 disposal well today. No personnel or equipment was on location at the time of my inspection. Time of inspection: 12:50 PM. Weather: 62 degrees F, Sunny

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/13/2020

Signature: _____
BRANDON MITCHELL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner ARROWHEAD ROAD SERVICES LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297710000

Project:

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: ARROWHEAD ROAD SERVICES LLC Resp Co Same as Operator

Well Name: ARROWHEAD ROAD SERVICES LL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Drill / Deepen / Reopen Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact BRANDON MITCHELL

Inspection Comments:

I conducted an inspection of the well location today. During my inspection I spoke with employees of Gas Field Services LLC who were preparing to make some modifications to the well location with heavy equipment. Time of inspection: 8:50 AM.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/20/2020

Signature: _____
BRANDON MITCHELL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner ARROWHEAD ROAD SERVICES LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Preliminary Restoration Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact JOSH GARLAND

Inspection Comments:

Drilling pits have been filled, drilling equipment has been removed, areas of the site not essential to production have vegetative cover with no significant erosion, preliminary restoration complete.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/22/2020

Signature: _____
JOSH GARLAND

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Preliminary Restoration Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact JOSH GARLAND

Inspection Comments:

Preliminary restoration passed. Drilling pits filled, no erosion at site, drilling equipment removed.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 6/18/2020

Signature: _____
JOSH GARLAND

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump to this well was not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 700 Vac ANNULUSPRESSURE: 440 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/13/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that well is not being used much at this time, waitig on injection pump to be delivered from Baker Pump.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 240 Vac ANNULUSPRESSURE: 760 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/6/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 260 Vac ANNULUSPRESSURE: 940 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/20/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167274010000

Project: SWIW-2-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co Same as Operator

Well Name: DAVIS-HUFFMAN No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was not in operation and I was on site to witness mini annulus test on said well.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 10 Vac ANNULUSPRESSURE: 360 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/21/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed: 7/21/2020

Duration: _____ hrs Section/Name

Original Owner BIG INJUN OIL & GAS INC.

Former Owners

12/30/1982 118 BIG INJUN OIL & GAS INC GeoDate 12/30/82

12/13/1984 642 LOTHES OIL & GAS INC GeoDate 12/13/84

5/3/1989 3133 PETROEL GeoDate 5/3/89

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump to this well was not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 890 Vac ANNULUSPRESSURE: 300 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/13/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump to this well was not in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 900 Vac ANNULUSPRESSURE: 335 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/13/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1410 Vac ANNULUSPRESSURE: 610 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/20/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167279580000

Project: SWIW-9-WASH

County: WASHINGTON Twp. BARLOW Sec: 0 Lot: 0 WI Typ: SW_R

Owner: CARPER WELL SERVICE INC. Resp Co Same as Operator

Well Name: DAVIS-HUFFMAN(SWIW#9) No.: 3 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was not in operation and I was on site to witness mini annulus test on said well.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 0 Vac ANNULUSPRESSURE: 300 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/21/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed: 7/21/2020

Duration: _____ hrs Section/Name

Original Owner CARPER WELL SERVICE

Former Owners

12/20/1984 3133 PETROEL GeoDate 12/20/84

6/15/1998 Operator changed from 3133, PETROEL to 6158, JONES PERLEY E

2/3/1999 Operator changed from 6158, JONES PERLEY E to 3133, PETROEL

6/25/2001 Operator changed from 3133, PETROEL to 7007, CARPER WELL SERVICE

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump to this well was in operation during my inspection.

Noted: Two Gas field Services vacuum trucks were on site offloading during my inspection.

Accompanied by _____

INJECTIONPRESSUR 600 Vac ANNULUSPRESSURE: 300 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/13/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297680000

Project:

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: REDBIRD (SWIW #25) No.: 5 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Preliminary Restoration Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Pit has been closed and location roughed in owner currently installing outer flowline to well and injection line has been ordered and awaiting delivery once installed we will pressure test line and perform current MIT and then owner may request permission to inject.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 7/20/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297680000

Project:

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: REDBIRD (SWIW #25) No.: 5 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site today to witness pressure testing of 4" injection line and MIT testing on said well.

Tested injection line to 1160 psi with no decline in pressure and MIT test@1220 psi also with no decline.

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: 1220 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/13/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed: 8/13/2020

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297680000

Project:

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: REDBIRD (SWIW #25) No.: 5 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness new 4" injection line being pulled through outer casing from the number four well to the number five wellheads were fabricating wellhead today.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/6/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1240 Vac ANNULUSPRESSURE: 600 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 8/6/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

No activity on site to report.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 0 Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/3/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness parting of 4.5" casing shot number one@6884.5' didn't part came out of hole and worked pipe with no success then decision was made to go back in hole and try again at 6848' and then casing parted made sure casing was free and decision was made to shut down for the night and resume operation in the morning.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/6/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation during my inspection.

2-Hall Drilling tankers on site offloading during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1295 Vac ANNULUSPRESSURE: 15 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/24/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pumps were in operation during my inspection.

Noted one Gasfield Services tanker on site offloading during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1110 Vac ANNULUSPRESSURE: 380 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/29/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump was in operation during my inspection.

Noted that clean up has begun in area of temporary fluid cleaning site.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 840 Vac ANNULUSPRESSURE: 740 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/29/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump to this well was in operation during my inspection.

Looked over potential barge offload lines today looked at two 6" lines one will not pressure test and the other will hold 100 psi suggested that they may want to install new double encased lines for future use if they decide to move forward with brine barge offloading.

Accompanied by _____

INJECTIONPRESSUR 930 Vac ANNULUSPRESSURE: 850 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/25/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pumps were in operation during my inspection.

Note: Six ECM vacuum trucks on site offloading during my inspection.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 890 Vac ANNULUSPRESSURE: 160 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/16/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Well currently not in operation, injection pump is down for repair.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 240 Vac ANNULUSPRESSURE: 960 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/2/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1090 Vac ANNULUSPRESSURE: 725 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/25/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Currently drilling on cement retainer it wouldn't shut so decision was made to drill it out so we can run more tubing in well to spot required plug.

Note: Used 15.6 drilling fluid to kill well and drill out retainer with.

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/16/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Milling on cement inside of tubing drilled 800' of cement and then bond logged and it was determined that cement has tubing hung at 6186'-6000'.

Gladiator Energy services was coil tubing contractor and Energy Unlimited was service rig contractor.

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/22/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pumps were in operation during my inspection.

Noted one Gasfield Services tanker on site offloading during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 890 Vac ANNULUSPRESSURE: 625 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/29/2019

Signature: _____

Date Compliance Issued: _____

DAVID BALL

Required action to be completed by: _____

Reviewed by: _____

Extended action completed: _____

Forward to: _____

Required action completed: _____

Duration: _____ hrs

Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC

12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC

12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH
WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.

12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC

12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness milling up of float valve to confirm that we have a valid plug on bottom.

All flow equipment on site tested to 4000psi.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/24/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

KLX Wireline on site to cut off tubing@6601' just above float assembly and they will let it fall to bottom and they verified that it went down hole, and then they rigged coil tubing unit back up to run in hole to 7290' open ended and Formation Cementing mixed 4.5 bbl of 15# cement and coil unit pumped it to bottom and displaced and cement plug top should be at 6990' once cement is cured they will open up tubing valve to verify that well is dead and once that is verified wireline unit will run in well to tag cement top.

Accompanied by _____

INJECTION PRESSURE: Vac ANNULUS PRESSURE: Vac FLOWMETER: Vac

HAULER NO: LISCENSE_NUM:

LANDOWNER WAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/30/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Well has been plugged back to the SalinaG section of well bore and tested with low volume of potential injection zone, talked to company rep and she stated that company would likely plan on plugging well to surface and abandon well project.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: 1400 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/15/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump was in operation during my inspection.

Note: New filter system has been installed since my last inspection.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1200 Vac ANNULUSPRESSURE: 170 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/21/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation during my inspection and it was noted that two Hall Drilling tankers were on site offloading during my time on site.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1410 Vac ANNULUSPRESSURE: 680 Vac FLOWMETER: Vac

HAULERNO: 25361 LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/25/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Pulling remaining 4.5" casing from wellbore.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/9/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Milling on float valve system on bottom of tubing string.

1.87 flat bottom mill.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/25/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Ran new flat bottom mill bit in hole with coil tubing and milled for 3 hours can out of hole and three small pieces of flat metal was stuck in mill, ran back in hole with new mill and continued to mill float valve assembly.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/26/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co Same as Operator

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Address

Inspection Purpose: Status Check

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pumps were in operation during my inspection.

Note: Walked flowline area today.

Accompanied by _____

INJECTIONPRESSUR 1205 Vac ANNULUSPRESSURE: 170 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/21/2019

Signature:

Date Compliance Issued:

DAVID BALL

Required action to be completed by:

Reviewed by:

Extended action completed:

Forward to:

Required action completed:

Duration: _____ hrs

Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site today to finish killing well and spot bottom hole plug, had to wait on kill fluid to arrive on site it was supposed to be **on site@9 am didn't show up until after noon on it was on site coil tubing was lowered back to bottom and well was killed** they monitored well for one hour and then decision was made to mix cement plug and displace to bottom a total of 32 sacks of Class A cement with a weight of 15.6 ppg and kill fluid was used for displacement 19.1 bbl. Plug is at 7275'-6900' top of plug well was shut in after coil was removed from hole.
Will tag cement plug in a couple days.

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/17/2019

Date Compliance Issued: Signature: DAVID BALL

Required action to be completed by: Reviewed by:

Extended action completed: Forward to:

Required action completed: Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that coil tubing unit was rigging back up on well and once rigged up they pressure tested and started in hole open ended and they sat down at 5100' decision was made to come out of hole and place a 1.87" mill on and go back in hole tomorrow morning and clean out obstruction to bottom.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/14/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site to witness setting of 350' cement plug inside of the 7" casing(plug set@6825'-6475') 71 sacks of Class A cement and displaced with 25 bbl. of fresh water 2.375" tubing used to set plug, will confirm cement top later this week after cement has time to set up.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/10/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation during my inspection.

2-Hall Drilling tankers on site offloading during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1330 Vac ANNULUSPRESSURE: 15 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/24/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone
Address

Inspection Purpose: Status Check

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pumps were in operation during my inspection.

Note: Six ECM vacuum trucks on site offloading during my inspection.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1400 Vac ANNULUSPRESSURE: 50 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/16/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Well currently not in operation.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 260 Vac ANNULUSPRESSURE: 620 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/24/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump was not in operation during my inspection.

Note: New filter system has been installed since my last inspection.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 380 Vac ANNULUSPRESSURE: 800 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/21/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone
Address

Inspection Purpose: Status Check

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pumps were in operation during my inspection.

Note: Six ECM vacuum trucks on site offloading during my inspection.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1370 Vac ANNULUSPRESSURE: 115 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/16/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Witness setting of bottom hole plug, 25 sack plug set @7310-7000 pulled tubing up above plug and will tag plug tomorrow according to plugging contractor

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/18/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pumps were in operation during my inspection.

Note: Six ECM vacuum trucks on site offloading during my inspection.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1390 Vac ANNULUSPRESSURE: 280 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/16/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site today to witness Unlimited Energy Services run wireline magnet to top of float assembly and pull debris from inside of tubing.

Made a total of six wireline magnet runs today.

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/28/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site today to witness perforating of tubing to see if there was pressure on wellbore below float assembly KLX shot one 1/4" hole and we had pressure on tubing, decision was made to shot tubing off tomorrow and let assembly fall to bottom and then run coil back in hole to set bottom hole plug.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/29/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

No activity on site today, going to move coil tubing unit back on site 11/14/2019 to run back to bottom and kill well and then reset bottom hole plug.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/12/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

No activity at the site today, coil tubing unit coming back on site 11/14/19 to attempt to set bottom hole plug for the third time.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: 0 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/12/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site today to attempt to set bottom hole plug, loaded hole with 15.8ppg kill fluid ran out of usable kill fluid had wellhead pressure down to 427 psi had to order more fluid and will resume operations in the morning.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/16/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295770000

Project: SWIW-7-WASH

County: WASHINGTON Twp. LAWRENCE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: FQ ENERGY SERVICES LLC Resp Co Same as Operator

Well Name: HELEN F HALL (SWIW #7) No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that well is still down waiting on plug/repair work performed on well.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 580 Vac ANNULUSPRESSURE: 780 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/25/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner FQ ENERGY SERVICES LLC

Former Owners

10/24/2014 Operator changed from 7434, VIRCO INC to 8896, GREEN HUNTER WATER LLC

5/20/2016 Operator changed from 8896, GREEN HUNTER WATER LLC to 9679, FQ ENERGY SERVICES LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Stopped by service rig to check on them pulling 4.5" casing was cut off @6848' and pipe is extremely tight tongs are crushing pipe as they try and break it, possibly have to get casing string replaced once they recompleat well to upper potential injection zone.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/8/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Set plug and pull casing out of hole.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/11/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site today to pressure test cement plug they tested at 1840 psi and we monitored pressure for 15 minutes with no decline in pressure and once test completed then they ran in hole with a cast iron bridge plug and setting depth was at 6470' and top of cement plug was noted at 6500' which was 25' below the calculated top of 6475.'

Maximum injection pressure will be 1460 psi and they tested cement plug@1.25 times maximum pressure equals 1825 psi.

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/15/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Appalachian Well Services on site to perforate casing in the Salina G section of wellbore 80 shots from 6340-6360.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/17/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site today to witness new Hornet type packer and new 11.6# per foot 4.5" casing run into well Key Energy ran 91 joints of pipe today will resume operations tomorrow.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/18/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Stopped by well site to check pressure on wellhead after setting packer it currently had 1100 psi on tubing and 1500 psi on the annulus.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1100 Vac ANNULUSPRESSURE: 1500 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/24/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297670000

Project: SWIW-24-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: REDBIRD (SWIW #24) No.: 4 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that well is still down for pump repair.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 225 Vac ANNULUSPRESSURE: 960 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/25/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Bond log well, tubing hung at 6186'-6004' tubing was cleaned out to 6619' and tubing total is 6030' decision was made to drill float valve out to confirm that cement plug is present or not.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/23/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Washing coil tubing back to bottom, well took approximately 200 bbl. today sat down @7287' tried to do injection test at 1970 psi well would only take .3 bpm.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/15/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co Same as Operator

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Injection pump was in operation during my inspection, no truck activity on site during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1150 Vac ANNULUSPRESSURE: 255 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/29/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone
Address

Inspection Purpose: Status Check

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was not in operation during my inspection.

Noted two Hall Drilling tankers on site during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 865 Vac ANNULUSPRESSURE: 1350 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/25/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167238620000

Project: SWIW-13-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: HECKMANN WATER RESOURCES (CVR) INC Resp Co Same as Operator

Well Name: NICHOLS (SWIW #13) No.: 1-A WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site today to witness MIT testing of said well .
Injection pressure today was noted at 1020 psi and annulus pressure prior to test was noted at 60 psi and pressure on
8.625" was noted at 180 psi.

Specific gravity noted@1.12

Accompanied by _____

INJECTIONPRESSUR 1020 Vac ANNULUSPRESSURE: 1240 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/28/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed: 1/28/2020

Duration: _____ hrs Section/Name

Original Owner NICHOLS DISPOSAL WELL LLC

Former Owners

8/5/1977 521 CONSTITUTION PETROLEUM GeoDate 8/5/77

6/15/2011 Operator changed from 521, CONSTITUTION PETROLEUM to 8821, NICHOLS DISPOSAL WELL LLC

8/2/2012 Operator changed from 8821, NICHOLS DISPOSAL WELL LLC to 8981, HECKMAN WATER RES(CVR)INC. O&

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167295430000

Project: SWIW-20-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: VOCATIONAL SCHOOL UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pumps were in operation during my inspection.

Noted one Gasfield Services tanker on site offloading during my inspection.
Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1315 Vac ANNULUSPRESSURE: 720 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 11/29/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. T WELL WAS NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294450000

Project: SWIW-21-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: HEINRICH UNIT No.: 1 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation during my inspection.

2-Hall Drilling tankers on site offloading during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1285 Vac ANNULUSPRESSURE: 10 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/24/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. TH WELLS WERE NOT INCLUDED IN THE EXCO TO ENERVEST TRANSFER.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167294640000

Project: SWIW-22-WASH

County: WASHINGTON Twp. WARREN Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: HEINRICH UNIT No.: 2 (SWIW WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1050 Vac ANNULUSPRESSURE: 410 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/25/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner HEINRICH ENT INC/WASHINGTON OP

Former Owners

- 2/27/2008 Operator changed from 3793, ENERGY SEARCH INC to 1388, NORTH COAST ENERGY INC
- 12/14/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 7578, ENERVEST OPERATING LLC
- 12/30/2009 Operator changed from 7578, ENERVEST OPERATING LLC to 1388, EXCO - NORTH COAST ENERGY INC. THIS WAS NOT INCLUDED IN THE TRANSFER FROM EXCO TO ENERVEST.
- 12/30/2009 Operator changed from 1388, EXCO - NORTH COAST ENERGY INC to 2007, HEINRICH ENTERPRISES INC
- 12/29/2017 Operator changed from 2007, HEINRICH ENT INC/WASHINGTON OP to 9896, DEEPROCK DISPOSAL SOLUT

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167296580000

Project: SWIW-8-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: LONG RUN DISPOSAL WELL(SWI No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today revealed that well is currently in operation.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1750 Vac ANNULUSPRESSURE: 520 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/3/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OHIO OIL GATHERING CORP

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167284620000

Project: SWIW-4-WASH

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: M & R INVESTMENTS OHIO LLC Resp Co Same as Operator

Well Name: FLOWER HL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site today to witness owner change out injection pump and then dig up around wellhead so I could possibly check annular pressure on 8.625" wellhead it was discovered that 4.5" casing is set on slip bowl type head and annulus between 4.5" and 8.62 was open no signs of any leaks, suggested to owner they might want to place a sealed wellhead on 8" in case they would ever have a casing leak above cement top water could potentially come to surface.

Accompanied by _____

INJECTIONPRESSUR 780 Vac ANNULUSPRESSURE: 120 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 2/4/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OMEGA BRINE 88-2 LTD.

Former Owners

12/9/1986 2497 FARR ENTERPRISES INC GeoDate 12/9/86

4/11/1989 3294 OMEGA BRINE 88-2 LTD GeoDate 4/11/89

9/8/1989 1619 BROWN PHILLIP OIL & GAS GeoDate 9/8/89

11/13/1995 4350 CENTURY WELL SERVICE GeoDate 9/8/89

10/3/2007 Operator changed from 4350, CENTURY WELL SERVICE to 7033, BROAD STREET ENERGY COMPANY

2/19/2008 Operator changed from 7033, BROAD STREET ENERGY COMPANY to 8312, BROAD STREET SERV LLC

7/16/2015 Operator changed from 8312, BROAD STREET SERV LLC to 8685, M & R INVESTMENTS OHIO LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site today to witness running of the remainder of the injection string in hole and set packer@6303' center of element and then we circulated annulus of tubing with 117 bbl. of fresh water and 10 gallon of inhibitor and we tested it at 1526 psi and we had a 15 psi pressure loss during test period (TEST PASSED) and once test period was over they pumped test plug off the bottom of tubing it took 3332 psi to release blank plug

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LICENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/19/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297310000

Project: SWIW-18-WASH

County: WASHINGTON Twp. DUNHAM Sec: 0 Lot: 0 WI Typ: SW_R

Owner: REDBIRD DEVELOPMENT LLC Resp Co Same as Operator

Well Name: RED BIRD (SWIW #18) No.: 2 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection revealed that injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 1235 Vac ANNULUSPRESSURE: 180 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/2/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner REDBIRD DEVELOPMENT LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Surface Facility Construction Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 780 Vac ANNULUSPRESSURE: 350 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 1/31/2020

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297660000

Project: WASH-SWIW-26

County: WASHINGTON Twp. MARIETTA Sec: 0 Lot: 0 WI Typ: SW_R

Owner: DEEPROCK DISPOSAL SOLUTIONS LLC Resp Co Same as Operator

Well Name: AMERICAN GROWERS (SWIW #26 No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Salt Water Injection Well Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

Inspection today indicated that injection pump was in operation during my inspection.

2-Hall Drilling tankers on site offloading during my inspection.

Inspection.CMMNT:

Accompanied by _____

INJECTIONPRESSUR 950 Vac ANNULUSPRESSURE: 370 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/24/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner DEEPROCK DISPOSAL SOLUTIONS LLC

Former Owners

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297190000

Project: SWIW-16-WASH

County: WASHINGTON Twp. NEWPORT Sec: 0 Lot: 0 WI Typ: SW_R

Owner: OOGC DISPOSAL COMPANY 1 LLC Resp Co Same as Operator

Well Name: SAWMILL RUN DISPOSAL (SWIW No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Plug / Plug Back Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact DAVID BALL

Inspection Comments:

On site today to witness Appalachian Wireline run in hole to confirm perforations were not covered up and then Producers Services performed acid treatment on said well, currently well does not appear to be wanting to take water within the maximum allowable pressure allowed .
Owner will need to apply for new permit if they want to try upper zones or apply for plugging permit.

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: 1500 Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 12/27/2019

Signature: _____
DAVID BALL

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner OOGC DISPOSAL COMPANY 1 LLC

Former Owners

11/24/2015 Operator changed from 2153, OOGC DISPOSAL CO 1 LLC to 9503, OOGC DISPOSAL COMPANY 1 LLC

Ohio Department of Natural Resources
Division of Mineral Resources Management
Facility Report

API Well No.

34167297710000

Project:

County: WASHINGTON Twp. BELPRE Sec: 0 Lot: 0 WI Typ: SW_R

Owner: ARROWHEAD ROAD SERVICES LLC Resp Co Same as Operator

Well Name: ARROWHEAD ROAD SERVICES LL No.: 1 WH_LAT 0.000000 WH_LONG: 0.000000

Directions to site:

Inspection Type: Casing String Witnessed Contact: Phone

Inspection Purpose: Status Check Address

Type of Notification Contact CHRISTIAN TAIT

Inspection Comments:

On this day, I met with Mr. Tom Roberts and witnessed cement operations for the 26 inch conductor casing that was cemented in 36 inch open hole. Express Energy Services drilled a 36 inch hole to a depth of 42 feet, and ran 42 feet of 26 inch conductor casing. Express Energy Services pumped 5 barrels of fresh water ahead, then pumped 103 sacks of class A neat cement with a yield of 1.18 and a weight of 15.6 pounds per gallon to surface.

Accompanied by _____

INJECTIONPRESSUR Vac ANNULUSPRESSURE: Vac FLOWMETER: Vac

HAULERNO: LISCENSE_NUM:

LANDOWNERWAIVER: P_REST_PASS: F_REST_PASS:

Inspection Date: 10/30/2020

Signature: _____
CHRISTIAN TAIT

Date Compliance Issued:

Required action to be completed by:

Reviewed by: _____

Extended action completed:

Forward to: _____

Required action completed:

Duration: _____ hrs Section/Name

Original Owner ARROWHEAD ROAD SERVICES LLC

Former Owners